

Customer Notification

QB-MINI2-EE

Universal Flash Memory Programmer and Serial On-chip Debugger

Operating Precautions

Notice

1. All information included in this document is current as of the date this document is issued. Such information, however, is subject to change without any prior notice. Before purchasing or using any Renesas Electronics products listed herein, please confirm the latest product information with a Renesas Electronics sales office. Also, please pay regular and careful attention to additional and different information to be disclosed by Renesas Electronics such as that disclosed through our website.
2. Renesas Electronics does not assume any liability for infringement of patents, copyrights, or other intellectual property rights of third parties by or arising from the use of Renesas Electronics products or technical information described in this document. No license, express, implied or otherwise, is granted hereby under any patents, copyrights or other intellectual property rights of Renesas Electronics or others.
3. You should not alter, modify, copy, or otherwise misappropriate any Renesas Electronics product, whether in whole or in part.
4. Descriptions of circuits, software and other related information in this document are provided only to illustrate the operation of semiconductor products and application examples. You are fully responsible for the incorporation of these circuits, software, and information in the design of your equipment. Renesas Electronics assumes no responsibility for any losses incurred by you or third parties arising from the use of these circuits, software, or information.
5. When exporting the products or technology described in this document, you should comply with the applicable export control laws and regulations and follow the procedures required by such laws and regulations. You should not use Renesas Electronics products or the technology described in this document for any purpose relating to military applications or use by the military, including but not limited to the development of weapons of mass destruction. Renesas Electronics products and technology may not be used for or incorporated into any products or systems whose manufacture, use, or sale is prohibited under any applicable domestic or foreign laws or regulations.
6. Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.
7. Renesas Electronics products are classified according to the following three quality grades: "Standard", "High Quality", and "Specific". The recommended applications for each Renesas Electronics product depends on the product's quality grade, as indicated below. You must check the quality grade of each Renesas Electronics product before using it in a particular application. You may not use any Renesas Electronics product for any application categorized as "Specific" without the prior written consent of Renesas Electronics. Further, you may not use any Renesas Electronics product for any application for which it is not intended without the prior written consent of Renesas Electronics. Renesas Electronics shall not be in any way liable for any damages or losses incurred by you or third parties arising from the use of any Renesas Electronics product for an application categorized as "Specific" or for which the product is not intended where you have failed to obtain the prior written consent of Renesas Electronics. The quality grade of each Renesas Electronics product is "Standard" unless otherwise expressly specified in a Renesas Electronics data sheets or data books, etc.

"Standard": Computers; office equipment; communications equipment; test and measurement equipment; audio and visual equipment; home electronic appliances; machine tools; personal electronic equipment; and industrial robots.

"High Quality": Transportation equipment (automobiles, trains, ships, etc.); traffic control systems; anti-disaster systems; anti-crime systems; safety equipment; and medical equipment not specifically designed for life support.

"Specific": Aircraft; aerospace equipment; submersible repeaters; nuclear reactor control systems; medical equipment or systems for life support (e.g. artificial life support devices or systems), surgical implantations, or healthcare intervention (e.g. excision, etc.), and any other applications or purposes that pose a direct threat to human life.
8. You should use the Renesas Electronics products described in this document within the range specified by Renesas Electronics, especially with respect to the maximum rating, operating supply voltage range, movement power voltage range, heat radiation characteristics, installation and other product characteristics. Renesas Electronics shall have no liability for malfunctions or damages arising out of the use of Renesas Electronics products beyond such specified ranges.
9. Although Renesas Electronics endeavors to improve the quality and reliability of its products, semiconductor products have specific characteristics such as the occurrence of failure at a certain rate and malfunctions under certain use conditions. Further, Renesas Electronics products are not subject to radiation resistance design. Please be sure to implement safety measures to guard them against the possibility of physical injury, and injury or damage caused by fire in the event of the failure of a Renesas Electronics product, such as safety design for hardware and software including but not limited to redundancy, fire control and malfunction prevention, appropriate treatment for aging degradation or any other appropriate measures. Because the evaluation of microcomputer software alone is very difficult, please evaluate the safety of the final products or system manufactured by you.

10. Please contact a Renesas Electronics sales office for details as to environmental matters such as the environmental compatibility of each Renesas Electronics product. Please use Renesas Electronics products in compliance with all applicable laws and regulations that regulate the inclusion or use of controlled substances, including without limitation, the EU RoHS Directive. Renesas Electronics assumes no liability for damages or losses occurring as a result of your noncompliance with applicable laws and regulations.
11. This document may not be reproduced or duplicated, in any form, in whole or in part, without prior written consent of Renesas Electronics.
12. Please contact a Renesas Electronics sales office if you have any questions regarding the information contained in this document or Renesas Electronics products, or if you have any other inquiries.

(Note 1) "Renesas Electronics" as used in this document means Renesas Electronics Corporation and also includes its majority- owned subsidiaries.

(Note 2) "Renesas Electronics product(s)" means any product developed or manufactured by or for Renesas Electronics.

Table of Contents

- A) Table of Operating Precautions5
- B) Description of Operating Precautions6
- C) Product Version15
- D) Supported Devices16
 - a) 78K0 microcontrollers.....16
 - b) 78K0S microcontrollers17
 - c) 78K0R microcontrollers17
 - d) V850 microcontrollers.....17
- E) Valid Specification19
- F) Revision History20

A) Table of Operating Precautions

Table A-1 Table of Operating Precautions

No.	Target Device	Debug/ Progr.	Outline	Control Code: Firmware:	QB-MINI2-EE							
					A V4.00	A V4.01	A V4.02	A V4.03	A V4.04	A V4.05	A V4.07	A V5.00
1	78K0	Debug	Invalid internal high-speed RAM area after RESET	x	x	x	x	x	x	x	x	x
2	V850	Debug	Use of watchdog timer	x	x	x	x	x	x	x	x	x
3	V850	Debug	Break during sub-clock operation	x	x	x	x	✓	✓	✓	✓	✓
4	V850	Debug	Break during flash memory modifications	x	x	x	x	x	x	x	x	x
5	V850	Debug	Reset vector handling	x	x	x	x	x	x	x	x	x
6	V850	Debug	Modifying specific registers	x	x	x	x	x	x	x	x	x
7	V850	Debug	Reset generation	x	x	x	x	x	x	x	x	x
8	78K0S	Debug	Debugging with operation clock of 6MHz or lower	✓	✓	✓	✓	✓	✓	✓	✓	✓
9	78K0S	Debug	Downloading when operation clock is 10MHz	x	✓	✓	✓	✓	✓	✓	✓	✓
10	78K0S	Debug	Display of register values	✓	✓	✓	✓	✓	✓	✓	✓	✓
11	78K0R	Debug	Breakpoint for a CPU lower than 2MHz	x	x	✓	✓	✓	✓	✓	✓	✓
12	78K0R	Debug	Debugging of time measurement function in 1-wire mode	x	x	✓	✓	✓	✓	✓	✓	✓
13	78K0R	Debug	Invalid operation after program download	x	x	✓	✓	✓	✓	✓	✓	✓
14	78K0R	Debug	Using QB-MINI2-EE with USB1.1	x	x	x	✓	✓	✓	✓	✓	✓
15	78K0R	Debug	Operation at frequencies at 20MHz	x	x	x	✓	✓	✓	✓	✓	✓
16	78K0R	Debug	General purpose registers after reset	x	x	x	x	x	x	x	x	x
17	78K0R	Debug	Specification changes in conjunction with firmware optimization	-	-	-	✓	✓	✓	✓	✓	✓
18	78K0R	Debug	Hardware breakpoints	x	x	x	x	x	x	x	x	x
19	V850	Debug	Download speed via CSI	-	-	-	-	✓	✓	✓	✓	✓
20	V850	Debug	Reserved area changed for CSI	-	-	-	-	✓	✓	✓	✓	✓
21	V850	Debug	Operation in low voltage	-	-	-	-	x	x	x	x	x
22	78K0R	Debug	Addition of specification of RRM and DDM functions	-	-	-	-	-	✓	✓	✓	✓
23	78K0	Debug Progr.	Devices with TOOLCx and TOOLDx pins	-	-	-	-	-	-	-	✓	✓
24	All	Debug Progr.	Addition of specification for support of MINICUBE2 wireless unit (QB-MINI2-RF)	-	-	-	-	-	-	-	-	✓

- : Not relevant or the target device is not supported
- ✓ : Not applicable or new/changed specification applies
- x : Applicable

B) Description of Operating Precautions

Table B-1 Invalid internal high-speed RAM area after RESET

<p><u>Details</u> If a RESET signal is generated at the RESET-pin or a RESET occurs due to POC during program execution, below showed internal high-speed RAM areas become invalid:</p> <ul style="list-style-type: none"> - 5 bytes from FECBh to FECFh (When Permit is selected in Target Power OFF field in the configuration dialog box) - 10 bytes from FEC9h to FECFh and FEDDh to FEDFh (When Not Permit is selected in Target Power OFF field in the configuration dialog box) <p><u>Workaround</u> No workaround available</p>

Table B-2 Use of watchdog timer

<p><u>Details</u> The watchdog timer cannot be used, because it's forcibly stopped by the debug monitor program. Don't set the option byte to disable watchdog timer stop.</p> <p><u>Workaround</u> No workaround available</p>

Table B-3 Break during sub-clock operation

<p><u>Details</u> In the configuration dialog box of the debugger it's possible to define, if the operating clock during a break is switched from sub-clock to main clock. But if UART is the communication channel between QB-MINI2-EE and target device, an occurring break during sub-clock operation (while the main clock has been stopped) will forcibly switch the operation clock to main clock. The device continues its operation with the main clock after monitor program execution.</p> <p><u>Workaround</u> No workaround available</p>

Table B-4 Break during flash memory modifications

<p><u>Details</u> A break may occurs at an unexpected address during flash memory modifications (for example usage of flash self-programming libraries).</p> <p><u>Workaround</u> No workaround available</p>

Table B-5 Reset vector handling

<p><u>Details</u> The reset vector cannot be used.</p> <p><u>Workaround</u> No workaround available</p>

Table B-6 Modifying specific registers

<p><u>Details</u> Peripheral I/O registers (except PCC and CKC), that require a specific program sequence for access, cannot be modified in the I/O register of the debugger.</p> <p><u>Workaround</u> No workaround available</p>
--

Table B-7 Reset generation

<p><u>Details</u> A break occurs, when an external reset (which isn't masked in the debugger GUI) or an internal reset is generated.</p> <p><u>Workaround</u> No workaround available</p>

Table B-8 Debugging with operation clock of 6MHz or lower

<p><u>Target Device</u> 78K0S</p> <p><u>Details</u> The debugger does not start when the target device operating frequency is 6MHz or lower</p> <p><u>Workaround</u> No workaround available This item is corrected from firmware version V4.00 onwards</p>

Table B-9 Downloading when operation clock is 10MHz

<p><u>Target Device</u> 78K0S</p> <p><u>Details</u> When the target device operating frequency is 10MHz, an error will occur during download of a program and the downloading cannot be completed.</p> <p><u>Workaround</u> No workaround available</p>

Table B-10 Display of register values

<p><u>Target Device</u> 78K0S</p> <p><u>Details</u> Register values may be displayed incorrectly in the debugger during a break.</p> <p><u>Workaround</u> No workaround available. This item is corrected in firmware version V4.00</p>

Table B-11 Table description

<p><u>Target Device</u> 78K0R</p> <p><u>Details</u> If a break occurs, during CPU operational clock lower than 2MHz, the internal flash memory can no longer be rewritten. The following operations cannot be performed any longer.</p> <ol style="list-style-type: none"> 1. Writing to internal Flash memory 2. Setting or canceling of software breakpoints 3. Starting execution at the set software breakpoint position 4. Step execution at the set software breakpoint position 5. Step-over execution, Return Out execution 6. Run to Cursor 7. If Permit of 'Flash memory access in the Flash Programming area', is selected in the Configuration dialog box, the following operations cannot be performed. <ol style="list-style-type: none"> a. Setting, changing, or canceling of hardware breaks b. Masking/unmasking of internal reset c. Switching of peripheral breaks <p><u>Workaround</u> To set a breakpoint, for operation performed at a CPU clock lower than 2MHz, use a hardware break and not a software breakpoint</p>
--

Table B-12 Debugging of time measurement function in 1-wire mode

<p><u>Target Device</u> 78K0R</p> <p><u>Details</u> When debugging is performed in 1-wire mode (selected by choosing TOOL0 in the Target Device Connection area in the configuration dialog box of the debugger), the Run-Break execution time is measured with the accuracy of about 10ms.</p> <p><u>Workaround</u> Perform debugging in 2-wire mode (TOOL0 + TOOL1)</p>

Table B-13 Invalid operation after program download

<p><u>Target Device</u> 78K0R</p> <p><u>Details</u> When the reset vector (address 0 and 1) points to an address lower than 0x0100, the debugger operation becomes invalid after a program is downloaded. Specifically, illegal breaks occur immediately after execution, the source window cannot be opened, and the application cannot be debugged.</p> <p><u>Workaround</u> <i>Assign the reset vector for the user program to addresses of 0x0100 or higher.</i></p>
--

Table B-14 Using QB-MINI2-EE with USB1.1

<p><u>Target Device</u> 78K0R</p> <p><u>Details</u> The debugger operation may become invalid if it is connected via USB 1.1.</p> <p><u>Workaround</u> <i>This item has been corrected in firmware V4.03.</i></p>

Table B-15 Operation on frequencies ≥ 20 MHz

<p><u>Target Device</u> 78K0R</p> <p><u>Details</u> When the QB-MINI2 operates at a frequency of 20 MHz or higher, downloading or manipulation to change the memory contents may fail.</p> <p><u>Workaround</u> Perform downloading or manipulation to change the memory contents at a frequency lower than 20MHz. <i>This item has been corrected in firmware V4.03.</i></p>

Table B-16 General purpose registers after reset

<p><u>Target Device</u> 78K0R</p> <p><u>Details</u> After reset in standby mode, the general register contents are not retained.</p> <p><u>Workaround</u> No workaround available</p>

Table B-17 Specification changes in conjunction with firmware optimization

<p><u>Target Device</u> 78K0R</p> <p><u>Details</u> The specifications shown below have been changed or added in conjunction with firmware optimization. This item has been implemented in firmware V4.03. To apply this correction, use the NEC Electronics debugger ID78K0R-QB V3.30 or later.</p> <ol style="list-style-type: none"> 1. The debugger operation speed has been improved by improving the MINICUBE2 firmware processing. 2. The operation speed in 1-wire mode has been improved to be equalized with that in 2-wire mode. 3. For a case when the pseudo real-time monitor function (RRM function) is not used during debugging in 2-wire mode, the occupied size of the debug monitor program allocated to the last block in the internal ROM has been reduced from 1 KB to 88 bytes. 4. Instructions that perform two instructions during step-wise execution have been modified so as to perform only one instruction. 5. The option byte setting (C1H) for the LVI default start function is now the same regardless of whether MINICUBE2 is connected. 6. Debugger operations for rewriting the flash memory (download, software break setting, etc.), which were not possible when the target microcontroller cannot rewrite the flash memory due to the CPU clock or the regulator mode, are now available by changing the specification so that the debugger automatically changes the SFR contents so as to enable rewriting of the flash memory to enable such operations. (Correction of restriction No. 11 is also included in this change). After rewriting the flash memory is completed, the SFR contents will be restored. The debugger will output the following errors if the operation voltage is lower than the voltage with which flash memory rewriting is possible (1), or if the flash memory rewriting is prohibited by the debugger configuration (2). (When using the ID78K0R-QB) <ul style="list-style-type: none"> In case of (1): "F0C37: The voltage is too low to operate flash programming." In case of (2): "F0C48: Flash programming is disabled in the debugger." In case of (1) or (2) and when setting or cancelling software breaks: <ul style="list-style-type: none"> "W401C: Software break can not be set on this area." 7. A break, which was generated if STOP mode is entered when the pseudo RRM function is used, is now prevented by releasing the STOP mode. <p><u>Workaround</u> No workaround available</p>

Table B-18 Hardware breakpoints

<p><u>Target Device</u> 78K0R</p> <p><u>Details</u> A hardware break occurs at an address several instructions after the specified point. This applies to both instruction fetch and data access. If any of the following debugger operations <1> to <3> is performed while the flash memory cannot be rewritten, a hardware break occurs at an address several instructions after the specified point.</p> <ol style="list-style-type: none"> 1. Step-wise execution 2. Return Out execution 3. Come Here. <p><u>Workaround</u> No workaround available</p>

Table B-19 Download speed via CSI

<p><u>Target Device</u> V850</p> <p><u>Details</u> The downloading speed via the CSI interface with the target system has been approximately doubled. This specification change is applicable for firmware V4.04 or later.</p> <ul style="list-style-type: none"> - Using the GHS Multi debugger, use the 850eserv V12.0 or later - Using the IAR debugger, use the IAR workbench V3.40 or later <p><u>Workaround</u> No workaround available</p>

Table B-20 Reserved area changed for CSI

<p><u>Target Device</u> V850ES/IE2</p> <p><u>Details</u> The reception error interrupt can now be used with Minicube2 when connected to the target system via CSI interface. The change has been implemented for the purpose of preventing debugger hang-up when a reception error occurs. This specification change is applicable for firmware V4.04 or later. - Using the GHS Multi debugger, use the 850eserv V12.0 or later - Using the IAR debugger, use the IAR workbench V3.40 or later</p> <p>When using the latest V850eserv and IAR version, it does not start with the firmware V4.03 or earlier. Also be sure to upgrade the firmware to V4.04 or later, if the V850eserv and IAR version 3.40 is used and Minicube2 is connected to the target system with UART.</p> <p><u>Workaround</u> No workaround available</p>
--

Table B-21 Operation at low voltage

<p><u>Target Device</u> V850ES/JX3-L</p> <p><u>Details</u> When the operation voltage of less 2.7V, communication between Minicube2 and the target device cannot be performed correctly, and a malfunction occurs. Be sure to perform debugging at a voltage of at least 2.7V.</p> <p><u>Workaround</u> No workaround available</p>

Table B-22 Specification on RRM and DDM functions

<p><u>Target Device</u> 78K0R</p> <p><u>Details</u> The following specifications <1> to <3> have been added. These specifications are added to firmware V4.05 and later.</p> <p><1> The pseudo RRM function is now supported in 1-wire mode (supported only in 2-wire mode in older version)</p> <p><2> The entire memory space can now be monitored when using the pseudo RRM function. If the targets to be monitored are too numerous, the operability of the debugger may be affected because the monitoring speed is slow when using the pseudo RRM function in 1-wire mode. Therefore monitoring the by Watch window, rather than the memory window, is recommended.</p> <p><3> The direct memory modification (DDM) function is now supported. Along with this support, the contents in the RAM can now be changed during program execution. When changing the memory contents by using the DDM function, program execution is stopped. This means, that the memory contents are not changed in real time.</p>

Table B-23 Devices with TOOLCx and TOOLDx pins

<p><u>Target Device</u> 78K0</p> <p><u>Details</u> On-chip debugging and flash programming of devices that have the TOOLCx and TOOLDx pins can now be executed. This specification is added in firmware V4.07 and later. If you are using the NEC Electronics debugger ID78K0-QB, please switch to ID78K0-QB V3.10 or later.</p> <p><u>Workaround</u> When the ID78K0-QB is upgraded to V3.10, be sure to upgrade the firmware of the MINICUBE2 to V4.07 or later.</p>
--

Table B-24 Addition of specification for support of MINICUBE2 wireless unit (QB-MINI2-RF)

<p><u>Details</u> The wireless extension unit QB-MINI2-RF for MINICUBE2 is now supported. This specification is added to firmware V5.00 or later.</p> <p><u>Caution</u> This unit can be used for all 78K0S, 78K0, 78K0R, and V850 microcontrollers, but whether a microcontroller is supported varies depending on the version of the debugger used.</p>


C) Product Version

The “**Control Code**” is an alphabetic code used to identify the hardware of QB-MINI2-EE. It is the second digit from the left in the 10-digit serial number printed on the sticker attached to the bottom side of QB-MINI2-EE (if it has not been upgraded).

The “**Firmware**” (F/W) is a program embedded in the controller device of the QB-MINI2-EE. The F/W version is shown as Vx.xx.

The control code and firmware version can be checked with the QB-MINI2-EE diagnostic tool:

Figure 1



D) Supported Devices

The devices that are supported by QB-MINI2 are listed in the following tables.

a) 78K0 microcontrollers

The following table lists the support status for 78K0 microcontrollers. Support for the target device also differs depending on the version of the development tools.

Table D-1 Table of supported 78K0 devices

Supported Devices	On-chip Debugging						Flash Memory Programming			
	Firmware Version	ID78K0-QB Version	Device File Package		Debug Monitor Area Size		Firmware Version	QBP Version	Parameter File Package	
				Version	w/o RRM	w RRM				Version
78K0/Lx2	≥V1.00	≥V2.94	DF780397	≥V1.03	256 bytes	256 bytes	≥V1.00	≥V1.00	PRM78F0397	≥V1.02
78K0/Kx2	≥V1.00	≥V2.94	DF780547	≥V2.21	256 bytes	256 bytes	≥V1.00	≥V1.00	PRM78F0547	≥V1.07
78K0/Kx2-L	≥V4.07	≥V3.10	DF780588	≥V2.00	256 bytes	384 bytes	≥V4.07	≥V2.24	PRM78F0588	≥V1.01
78K0/lx2	≥V4.07	≥V3.10	DF780756	≥V1.00	256 bytes	384 bytes	≥V4.07	≥V2.24	PRM78F0756	≥V1.00
78K0/Kx1+	≥V4.01	≥V2.94	DF78F0148H	≥V3.00	256 bytes	256 bytes	≥V1.00	≥V1.00	PRM78F0148	≥V1.12
UPD78(F)0822B	Not supported						≥V1.00	≥V1.00	PRM78F0822	≥V1.00
78K0/Fx2	≥V4.01	≥V2.94	DF78F0893	≥V1.01	384 bytes	512 bytes	≥V1.00	≥V1.00	PRM78F0893	≥V1.04
78K0/Fx1+	≥V4.01	≥V2.94	DF78F0876	≥V1.10	256 bytes	384 bytes	≥V1.00	≥V1.00	PRM78F0876	≥V1.11
UPD78F0822B	Not supported						≥V1.00	≥V1.00	PRM78F0822	≥V1.00
UPD78F0711 UPD78F0712 UPD78F0714	≥V4.01	≥V2.94	DF78F0714	≥V1.10	256 bytes	384 bytes	≥V1.00	≥V1.00	PRM78F0714	≥V1.12
UPD78F0730	≥V4.01	≥V2.94	DF780731	≥V1.20	256 bytes	256 bytes	≥V1.00	≥V1.00	PRM78F0731	≥V1.03
UPD78F0862x	Not supported						≥V1.00	≥V1.00	PRM78F0862	≥V1.11
UPD179F11x UPD179F12x	≥V4.04	≥V2.94	DF179124	≥V1.00	256 bytes	256 bytes	≥V4.03	≥V2.22	PRM179F124	≥V1.00
78K0/Lx3	≥V4.01	≥V2.94	DF780495	≥V1.00	256 bytes	256 bytes	≥V4.03	≥V2.21	PRM78F0495	≥V1.01
78K/Kxx with LIN	Not supported						≥V1.00	≥V1.00	PRM78F8006H	≥V1.00
							≥V1.00	≥V1.00	PRM78F8016	≥V1.01
							≥V1.00	≥V1.00	PRM78F8020	≥V1.01
UPD78F8024 UPD78F8025	Not supported						≥V1.00	≥V1.00	PRM78F8025	≥V1.00

b) 78K0S microcontrollers

The following table lists the support status for 78K0S microcontrollers. Support for the target device also differs depending on the version of the development tools. Check the external interrupt pins that can be used as a communication interface between Minicube2 and the target device.

Table D-2 Table of supported 78K0S devices

Supported Devices	On-chip Debugging					Flash Memory Programming			
	Supported Serial Interface	Firmware Version	ID78K0-QB Version	Device File Package		Firmware Version	QBP Version	Parameter File Package	
					Version				Version
78K0S/KU1+	INTP1	≥V4.01	≥V2.90	DF789234	≥V3.20	≥V3.00	≥V1.00	PRM78F9234	≥V1.08
78K0S/KY1+									
78K0S/KA1+	INTP3								
78K0S/KB1+									
UPD78F9334	Not supported					≥V3.00	≥V1.00	PRM78F9334	≥V1.00

c) 78K0R microcontrollers

The following table lists the support status for 78K0R microcontrollers. Support for the target device also differs depending on the version of the development tools.

Table D-3 Table of supported 78K0R devices

Supported Devices	On-chip Debugging				Flash Memory Programming			
	Firmware Version	ID78K0-QB Version	Device File Package		Firmware Version	QBP Version	Parameter File Package	
				Version				Version
78K0R/Kx3	≥V4.03	≥V3.30	DF781188	≥V3.00	≥V4.00	≥V2.00	PRM-78F1188	≥V1.01
78K0R/KC3-L	≥V4.05	≥V3.50	DF781014	≥V2.00	≥V4.03	≥V2.24	PRM78F1014	≥V1.01
78K0R/KD3-L								
78K0R/KE3-L								
78K0R/KF3-L	≥V5.00	≥V3.60	DF781014	≥V2.00	≥V4.03	≥V2.24	PRM78F1014	≥V1.01
78K0R/KG3-L								
78K0R/lx3	≥V5.00	≥V3.60	DF781235	≥V2.00	≥V4.03	≥V2.24	PRM78F1235	≥V1.00
78K0R/Lx3	≥V5.00	≥V3.60	DF781508	≥V1.00	≥V4.03	≥V2.24	PRM78F1508	≥V1.00
78K0R/Fx3	≥V5.00	≥V3.60	DF781845	≥V1.00	≥V4.03	≥V2.24	PRM78F1845	≥V1.00
78K0R/Kx3-C	≥V5.00	≥V3.60	DF781849	≥V1.00	≥V4.03	≥V2.24	PRM78F1849	≥V1.00

d) V850 microcontrollers

The following table lists the support status for V850 microcontrollers. Support for the target device also differs depending on the version of the development tools. Check the serial interface that can be used as a communication interface between Mini2 and the target device.

Table D-4 Table of supported V850 devices

Supported Devices	On-chip Debugging					Flash Memory Programming			
	Supported Interfaces	Firmware Version*	GHS eserv / IAR*	Device File Package		Firmware Version *	QBP Version*	Parameter File Package	
					Version*				Version*
V850ES/Hx2	UART0/CSIB0	V4.04	Vx.245/ V3.40	DF703712	V1.10	V2.00	V1.00	PRM70F3712	V1.00
V850ES/Hx3	UART0/CSIB0	V4.04	Vx.245/ V3.40	DF703757	V1.01	V4.04	V2.21	PRM70F3757	V1.00
V850ES/IE2	UART0/CSIB0	V4.04	Vx.245/ V3.40	DF703714	V1.00	V2.00	V1.00	PRM70F3714	V1.00
V850ES/Jx2	UART0 CSIB0/CSIB3	V4.04	Vx.245/ V3.40	DF703724	V1.00	V2.00	V1.00	PRM70F3724	V1.00
V850ES/Jx3	UART0 CSIB0/CSIB3	V4.04	Vx.245/ V3.40	DF703746	V1.00	V2.00	V1.00	PRM70F3746	V1.02
V850ES/Jx3-L	UART0 CSIB0/CSIB3	V4.04	Vx.245/ V3.40	DF703738	V1.10	V2.00	V1.00	PRM70F3738	V1.00
V850ES/Jx3-H	UART0 CSIB0/CSIB3	V4.04	Vx.245/ V3.40	DF703771	V1.00	V2.00	V1.00	PRM70F3771	V1.00
V850ES/Jx3-U	UART0 CSIB0/CSIB3	V4.04	Vx.245/ V3.40	DF703771	V1.00	V2.00	V1.00	PRM70F3771	V1.00
V850ES/Jx3-E	UART0 CSIF0/CSIF3	V5.00	Vx.245/ V3.60	DF703786	V1.00	Not supported			
V850ES/Kx2	UART0/CSIB0	V4.04	Vx.245/ V3.40	DF703734	V1.00	V2.00	V1.00	PRM70F3734	V1.01
V850ES/Kx1	Not supported					not supported			
V850ES/Kx1H	UART0 CSIB0	V4.04	Vx.245/ V3.40	DF703218	V2.01	V2.00	V1.00	PRM70F3218H	V1.11
V850ES/Kx1+	UART0 CSIB0	V4.04	Vx.245/ V3.40	DF703318	V1.01	V2.00	V1.00	PRM70F3318	V1.11
V850ES/Fx2	UARTA0/CSIB0	V4.04	Vx.245/ V3.40	DF703239	V2.13	V2.00	V1.00	PRM70F3239	V1.12
V850ES/Fx3	UARTD0/ CSIB0 ^{Note1}	V4.04	Vx.245/ V3.40	DF703385	V1.20	V4.00	V2.00	PRM70F3385	V1.02
V850ES/Fx3-L	UARTD0/ CSIB0 ^{Note1}	V4.04	Vx.245/ V3.40	DF703622	V1.00	V4.00	V2.00	PRM70F3622	V1.00
V850ES/Sx2	UART0 CSIB0/CSIB3	V4.04	Vx.245/ V3.40	DF703288	V2.11	V2.00	V1.00	PRM70F3288	V1.11
V850ES/Sx3	UART0 CSIB0/CSIB3	V4.04	Vx.245/ V3.40	DF703368	V1.01	V2.00	V1.00	PRM70F3368	V1.02
V850ES/SJ3-H V850ES/SK3-H	UART0 CSIB0/CSIB3	V5.00	Vx.245/ V3.60	DF703482	V1.00	V4.03	V2.24	PRM70F3482	V1.00
V850E/IA3 V850E/IA4	UARTA0/CSIB0	V4.04	Vx.245/ V3.40	DF703186	V3.00	V2.00	V1.00	PRM70F3184 PRM70F3186	V2.10
V850E/IF3 V850E/IG3	UARTA0/CSIB0	V4.04	Vx.245/ V3.40	DF703454	V1.00	V4.03	V2.21	PRM70F3454	V1.02
V850ES/IK1	UARTA0/CSIB0	V4.04	Vx.245/ V3.40	DF703329	V2.00	V2.00	V1.00	PRM70F3329	V1.20
V850ES/Dx2	Not supported					V2.00	V1.00	PRM70F3325	V1.10
V850ES/DG3 V850ES/DJ3	UARTA0/CSIB0	V5.00	Vx.245/ V3.60	DF703426	E2.00a	V2.01	V2.21	PRM70F3427	V1.00
V850E/MA3	UARTA0/CSIB0	V4.04	Vx.245/ V3.40	DF703134	V2.00	V2.00	V1.00	PRM70F3134	V1.21
V850E/SV2	Not supported					V2.00	V1.00	PRM70F3166	V1.10
V850E/PG2	Not supported					V2.00	V1.00	PRM70F3414	V1.00
V850E/PHO3	Not supported					V4.03	V2.21	PRM70F3441	V1.00

^{Note1} When using UARTD0, f_{RH} cannot be used as the CPU clock

* or higher version

E) Valid Specification

Item	Date published	Document No.	Document Title
1	June 2006 or later	U17966E	QB-MINI2-EE Setup Manual
2	March 2008 or later	U18371E	QB-MINI2-EE User's Manual

F) Revision History

Item	Date published	Document No.	Comment
1	June 2006	TPS-LE-OP-TMINI2-1	Release
2	August 2006	TPS-LE-OP-TMINI2-2	1 st Update: 78K0S restrictions added
3	October 2006	TPS-LE-OP-TMINI2-3	2 nd Update: 78K0R restrictions added
4	October 2006	TPS-LE-OP-TMINI2-4	3 rd Update: Revision of items 11, 12 and 13
5	March 2007	U18674EE1V0IF00	4 th Update: New Doc.-No. This document is a replacement of document TPS-LE-OP-TMINI2-4 Items 14 to 18 added Tables in Chapter (D) Supported Devices revised
6	April 2007	U18674EE2V0IF00	Items 19 and 20 added Tables in Chapter (D) supported devices revised
7	July 2008	U18674EE3V0IF00	Items 21 and 22 added Tables in Chapter (D) supported devices revised
8	May 2009	U18674EE4V0IF00	Item 23 added Tables in Chapter (D) supported devices revised
9	February 2010	U18674EE5V0IF00	Item 24 added Tables in Chapter (D) supported devices revised
10	October 2010	U18674EE6V0IF00	Table of supported V850 devices updated
11	Mai 2011	R01TU0019ED0100	Update of document number

