

September 30, 2010

To: Our Valued Customers

Attention: Procurement Manager

Subject: **PLC10100 – Product EOL/Obsolescence Notification**

You are hereby provided notice that the Intersil products included on the attached parts list are being discontinued. As a valued customer, and one that has previously purchased one or more of such parts, Intersil Corporation is pleased to offer you a final life-of-type procurement for these parts. Recognizing that you will need some time to analyze your requirements, Intersil will accept orders for these products through the LTB/WTHD date provided in the attached list. All shipments under such orders shall be scheduled no later than the SHIP/OBSOLETE date provided. Intersil will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please review the lists and make adjustments as necessary in your database.

The information contained herein is intended for the recipients use only. Please limit the distribution of this material to those individuals within your immediate organization having a need to act upon the information. In the event that additional distribution outside of your internal organization is necessary, please notify Intersil and the distribution list for discontinued products will be updated as appropriate.

If you are considering a redesign, and require assistance, please contact your local Sales or Rep office, or the Intersil Corporate Line, 1-888-468-3774, for our Central Applications Department.

*Carl Sapp*  
*GCCN Customer Relations Dept.*  
*Intersil Corporation*

Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB /	SHIP/	Similar/
being impacted.	Date	WTHD	OBSOLETE	Re-Design
		DATE	DATE	
AD7521LN	1-Oct-10	1-Apr-11	1-Oct-11	NONE
CA3054M96	1-Oct-10	1-Apr-11	1-Oct-11	CA3054MZ96
CA3083	1-Oct-10	1-Apr-11	1-Oct-11	CA3083Z
CA3083M96	1-Oct-10	1-Apr-11	1-Oct-11	CA3083MZ96
CA3102M	1-Oct-10	1-Apr-11	1-Oct-11	CA3102MZ
CA3127M	1-Oct-10	1-Apr-11	1-Oct-11	CA3127MZ
CA3130AE	1-Oct-10	1-Apr-11	1-Oct-11	CA3130AMZ, CA3130EZ, CA3130MZ
CA3130AM	1-Oct-10	1-Apr-11	1-Oct-11	CA3130AMZ
CA3130AM96	1-Oct-10	1-Apr-11	1-Oct-11	CA3130AMZ96
CA3130E	1-Oct-10	1-Apr-11	1-Oct-11	CA3130EZ
CA3130M	1-Oct-10	1-Apr-11	1-Oct-11	CA3130MZ
CA3130M96	1-Oct-10	1-Apr-11	1-Oct-11	CA3130MZ96
CA3140AE	1-Oct-10	1-Apr-11	1-Oct-11	CA3140AEZ
CA3140AM	1-Oct-10	1-Apr-11	1-Oct-11	CA3140AMZ
CA3140AM96	1-Oct-10	1-Apr-11	1-Oct-11	CA3140AMZ96
CA3140E	1-Oct-10	1-Apr-11	1-Oct-11	CA3140EZ
CA3140M	1-Oct-10	1-Apr-11	1-Oct-11	CA3140MZ
CA3140M96	1-Oct-10	1-Apr-11	1-Oct-11	CA3140MZ96
CA3240AE	1-Oct-10	1-Apr-11	1-Oct-11	CA3240AEZ
CA3240E	1-Oct-10	1-Apr-11	1-Oct-11	CA3240EZ
CA3260AE	1-Oct-10	1-Apr-11	1-Oct-11	CA3260AEZ
CA3260E	1-Oct-10	1-Apr-11	1-Oct-11	CA3260EZ
CA3338AE	1-Oct-10	1-Apr-11	1-Oct-11	CA3338AEZ
CA3338AM	1-Oct-10	1-Apr-11	1-Oct-11	CA3338AMZ
CA3338E	1-Oct-10	1-Apr-11	1-Oct-11	CA3338EZ
CA3338M	1-Oct-10	1-Apr-11	1-Oct-11	CA3338MZ
CA3420E	1-Oct-10	1-Apr-11	1-Oct-11	CA3420EZ
CA5260AM96	1-Oct-10	1-Apr-11	1-Oct-11	CA5260MZ96
CA5260M	1-Oct-10	1-Apr-11	1-Oct-11	CA5260MZ
CA5420AM	1-Oct-10	1-Apr-11	1-Oct-11	CA5420AMZ
CD22M3494E	1-Oct-10	1-Apr-11	1-Oct-11	CD22M3494EZ
CD22M3494MQ	1-Oct-10	1-Apr-11	1-Oct-11	CD22M3494MQZ
CD22M3494MQ96	1-Oct-10	1-Apr-11	1-Oct-11	CD22M3494MQZ96
DG211CJ	1-Oct-10	1-Apr-11	1-Oct-11	DG211CJZ
DG211CY	1-Oct-10	1-Apr-11	1-Oct-11	DG211CYZ
DG401DY	1-Oct-10	1-Apr-11	1-Oct-11	DG401DYZ
DG401DY-T	1-Oct-10	1-Apr-11	1-Oct-11	DG401DYZ-T
DG403DY	1-Oct-10	1-Apr-11	1-Oct-11	DG403DYZ
DG403DY-T	1-Oct-10	1-Apr-11	1-Oct-11	DG403DYZ-T
DG406DJ	1-Oct-10	1-Apr-11	1-Oct-11	DG406DJZ
DG406DY	1-Oct-10	1-Apr-11	1-Oct-11	DG406DYZ
DG406DY-T	1-Oct-10	1-Apr-11	1-Oct-11	DG406DYZ-T

Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB /	SHIP/	Similar/
being impacted.	Date	WTHD	OBSOLETE	Re-Design
		DATE	DATE	
DG407DJ	1-Oct-10	1-Apr-11	1-Oct-11	DG407DJZ
DG407DY	1-Oct-10	1-Apr-11	1-Oct-11	DG407DYZ
DG408DJ	1-Oct-10	1-Apr-11	1-Oct-11	DG408DJZ
DG408DY	1-Oct-10	1-Apr-11	1-Oct-11	DG408DYZ
DG408DY-T	1-Oct-10	1-Apr-11	1-Oct-11	DG408DYZ-T
DG409DJ	1-Oct-10	1-Apr-11	1-Oct-11	DG409DJZ
DG409DY	1-Oct-10	1-Apr-11	1-Oct-11	DG409DYZ
DG409DY-T	1-Oct-10	1-Apr-11	1-Oct-11	DG409DYZ-T
DG411DJ	1-Oct-10	1-Apr-11	1-Oct-11	DG411DJZ
DG411DY	1-Oct-10	1-Apr-11	1-Oct-11	DG411DYZ
DG411DY-T	1-Oct-10	1-Apr-11	1-Oct-11	DG411DYZ-T
DG412DJ	1-Oct-10	1-Apr-11	1-Oct-11	DG412DJZ
DG412DY	1-Oct-10	1-Apr-11	1-Oct-11	DG412DYZ
DG412DY-T	1-Oct-10	1-Apr-11	1-Oct-11	DG412DYZ-T
DG413DJ	1-Oct-10	1-Apr-11	1-Oct-11	DG413DJZ
DG413DY	1-Oct-10	1-Apr-11	1-Oct-11	DG413DYZ
DG413DY-T	1-Oct-10	1-Apr-11	1-Oct-11	DG413DYZ-T
DG441DY	1-Oct-10	1-Apr-11	1-Oct-11	DG441DYZ
DG441DY-T	1-Oct-10	1-Apr-11	1-Oct-11	DG441DYZ-T
DG442DY	1-Oct-10	1-Apr-11	1-Oct-11	DG442DYZ
DG442DY-T	1-Oct-10	1-Apr-11	1-Oct-11	DG442DYZ-T
DG444DY	1-Oct-10	1-Apr-11	1-Oct-11	DG444DYZ
DG444DY-T	1-Oct-10	1-Apr-11	1-Oct-11	DG444DYZ-T
DG445DY	1-Oct-10	1-Apr-11	1-Oct-11	DG445DYZ
DG445DY-T	1-Oct-10	1-Apr-11	1-Oct-11	DG445DYZ-T
EL1881CN	1-Oct-10	1-Apr-11	1-Oct-11	EL1881CSZ
EL1881CS	1-Oct-10	1-Apr-11	1-Oct-11	EL1881CSZ
EL1881CS-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL1881CSZ-T7
EL1883IS	1-Oct-10	1-Apr-11	1-Oct-11	EL1883ISZ
EL1883IS-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL1883ISZ-T7
EL2045CN	1-Oct-10	1-Apr-11	1-Oct-11	EL2045CSZ
EL2125CS	1-Oct-10	1-Apr-11	1-Oct-11	EL2125CSZ
EL2126CS-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL2126CSZ-T7
EL2227CS	1-Oct-10	1-Apr-11	1-Oct-11	EL2227CSZ
EL2250CS	1-Oct-10	1-Apr-11	1-Oct-11	EL2250CSZ
EL2480CS	1-Oct-10	1-Apr-11	1-Oct-11	EL2480CSZ
EL2480CS-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL2480CSZ-T7
EL4501IU	1-Oct-10	1-Apr-11	1-Oct-11	EL4501IUZ
EL4501IU-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL4501IUZ-T7
EL4511CU	1-Oct-10	1-Apr-11	1-Oct-11	EL4511CUZ
EL4581CN	1-Oct-10	1-Apr-11	1-Oct-11	EL4581CSZ
EL4581CS	1-Oct-10	1-Apr-11	1-Oct-11	EL4581CSZ
EL4581CS-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL4581CSZ-T7
EL4583AIS	1-Oct-10	1-Apr-11	1-Oct-11	EL4583AISZ

Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB /	SHIP/	Similar/
being impacted.	Date	WTHD	OBSOLETE	Re-Design
		DATE	DATE	
EL4583CN	1-Oct-10	1-Apr-11	1-Oct-11	EL4583CSZ
EL4583CS	1-Oct-10	1-Apr-11	1-Oct-11	EL4583CSZ
EL4583CS-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL4583CSZ-T7
EL4584CN	1-Oct-10	1-Apr-11	1-Oct-11	EL4584CSZ
EL4584CS	1-Oct-10	1-Apr-11	1-Oct-11	EL4584CSZ
EL4585CS	1-Oct-10	1-Apr-11	1-Oct-11	EL4585CSZ
EL5106IS	1-Oct-10	1-Apr-11	1-Oct-11	EL5106ISZ
EL5163IW-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL5163IWZ-T7
EL5167IW-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL5167IWZ-T7
EL5170IS	1-Oct-10	1-Apr-11	1-Oct-11	EL5170ISZ
EL5170IS-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL5170ISZ-T7
EL5170IY-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL5170IYZ-T7
EL5171IS	1-Oct-10	1-Apr-11	1-Oct-11	EL5171ISZ
EL5171IS-T13	1-Oct-10	1-Apr-11	1-Oct-11	EL5171ISZ-T13
EL5171IS-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL5171ISZ-T7
EL5172IS	1-Oct-10	1-Apr-11	1-Oct-11	EL5172ISZ
EL5172IS-T13	1-Oct-10	1-Apr-11	1-Oct-11	EL5172ISZ-T13
EL5172IY-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL5172IYZ-T7
EL5173IS	1-Oct-10	1-Apr-11	1-Oct-11	EL5173ISZ
EL5173IY-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL5173IYZ-T7
EL5174IS	1-Oct-10	1-Apr-11	1-Oct-11	EL5174ISZ
EL5175IS	1-Oct-10	1-Apr-11	1-Oct-11	EL5175ISZ
EL5192ACS	1-Oct-10	1-Apr-11	1-Oct-11	EL5192ACSZ
EL5205IS	1-Oct-10	1-Apr-11	1-Oct-11	EL5205ISZ
EL5263IS	1-Oct-10	1-Apr-11	1-Oct-11	EL5263ISZ
EL5308IS	1-Oct-10	1-Apr-11	1-Oct-11	NONE
EL5370IU	1-Oct-10	1-Apr-11	1-Oct-11	EL5370IUZ
EL5373IU	1-Oct-10	1-Apr-11	1-Oct-11	EL5373IUZ
EL6293CL-T13	1-Oct-10	1-Apr-11	1-Oct-11	EL6293CLZ-T13
EL7154CN	1-Oct-10	1-Apr-11	1-Oct-11	EL7154CNZ
EL7155CN	1-Oct-10	1-Apr-11	1-Oct-11	EL7155CSZ
EL7155CS	1-Oct-10	1-Apr-11	1-Oct-11	EL7155CSZ
EL7155CS-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL7155CSZ-T7
EL7156CN	1-Oct-10	1-Apr-11	1-Oct-11	EL7156CNZ
EL7156CS	1-Oct-10	1-Apr-11	1-Oct-11	EL7156CSZ
EL7156CS-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL7156CSZ-T7
EL7158IS	1-Oct-10	1-Apr-11	1-Oct-11	EL7158ISZ
EL7158ISE9045	1-Oct-10	1-Apr-11	1-Oct-11	EL7158ISZ-T7
EL7158ISE9045-T13	1-Oct-10	1-Apr-11	1-Oct-11	EL7158ISZ-T13
EL7158ISE9045-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL7158ISZ-T7
EL7457CS	1-Oct-10	1-Apr-11	1-Oct-11	EL7457CSZ
EL7457CU	1-Oct-10	1-Apr-11	1-Oct-11	EL7457CUZ
EL7457CU-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL7457CUZ-T7
EL8201IS	1-Oct-10	1-Apr-11	1-Oct-11	EL8201ISZ

Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB /	SHIP/	Similar/
being impacted.	Date	WTHD	OBSOLETE	Re-Design
		DATE	DATE	
EL8203IS	1-Oct-10	1-Apr-11	1-Oct-11	EL8203ISZ
EL8401IS	1-Oct-10	1-Apr-11	1-Oct-11	EL8401ISZ
EL9110IU	1-Oct-10	1-Apr-11	1-Oct-11	EL9110IUZ
EL9110IU-T7	1-Oct-10	1-Apr-11	1-Oct-11	EL9110IUZ-T7
EL9112IL	1-Oct-10	1-Apr-11	1-Oct-11	EL9112ILZ
HA1-2404-4	1-Oct-10	1-Apr-11	1-Oct-11	EL5165IC-T7A
HA1-2540-5	1-Oct-10	1-Apr-11	1-Oct-11	NONE
HA1-2556-9	1-Oct-10	1-Apr-11	1-Oct-11	NONE
HA1-4905-5	1-Oct-10	1-Apr-11	1-Oct-11	NONE
HA1-5320-5	1-Oct-10	1-Apr-11	1-Oct-11	NONE
HA1-5330-5	1-Oct-10	1-Apr-11	1-Oct-11	NONE
HA2-2525-5	1-Oct-10	1-Apr-11	1-Oct-11	HA2-2525-5ZR5254
HA2-2645-5	1-Oct-10	1-Apr-11	1-Oct-11	NONE
HA2-5002-5	1-Oct-10	1-Apr-11	1-Oct-11	HA2-5002/883, HA2-5002-2ZR5254
HA2-5160-5	1-Oct-10	1-Apr-11	1-Oct-11	NONE
HA3-2425-5	1-Oct-10	1-Apr-11	1-Oct-11	HA3-2525-5Z, HA3-5002-5Z, HA3-5020-5Z
HA3-2525-5	1-Oct-10	1-Apr-11	1-Oct-11	HA3-2525-5Z
HA3-2625-5	1-Oct-10	1-Apr-11	1-Oct-11	HA3-2525-5Z, HA3-5002-5Z, HA3-5020-5Z
HA3-5002-5	1-Oct-10	1-Apr-11	1-Oct-11	HA3-5002-5Z
HA3-5020-5	1-Oct-10	1-Apr-11	1-Oct-11	HA3-5020-5Z
HA3-5033-5	1-Oct-10	1-Apr-11	1-Oct-11	HA3-2525-5Z, HA3-5002-5Z, HA3-5020-5Z
HA3-5320-5	1-Oct-10	1-Apr-11	1-Oct-11	HA3-2525-5Z, HA3-5002-5Z, HA3-5020-5Z
HA4314BCA	1-Oct-10	1-Apr-11	1-Oct-11	HA4314BCAZ
HA4314BCB	1-Oct-10	1-Apr-11	1-Oct-11	HA4314BCBZ
HA4314BCB96	1-Oct-10	1-Apr-11	1-Oct-11	HA4314BCBZ96
HA4344BCB	1-Oct-10	1-Apr-11	1-Oct-11	HA4344BCBZ
HA456CM	1-Oct-10	1-Apr-11	1-Oct-11	HA456CMZ
HA4600CB	1-Oct-10	1-Apr-11	1-Oct-11	HA4600CBZ
HA4600CB96	1-Oct-10	1-Apr-11	1-Oct-11	HA4600CBZ96
HA4P5002-5	1-Oct-10	1-Apr-11	1-Oct-11	HA4P5002-5Z
HA5023IB	1-Oct-10	1-Apr-11	1-Oct-11	HA5023IBZ
HA5024IB	1-Oct-10	1-Apr-11	1-Oct-11	HA5024IBZ
HA5351IB	1-Oct-10	1-Apr-11	1-Oct-11	HA5351IBZ
HA7-2525-5	1-Oct-10	1-Apr-11	1-Oct-11	NONE
HA7-2645-5	1-Oct-10	1-Apr-11	1-Oct-11	NONE
HA7-5127A-5	1-Oct-10	1-Apr-11	1-Oct-11	HA7-5147R5254

Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB /	SHIP/	Similar/
being impacted.	Date	WTHD	OBSOLETE	Re-Design
		DATE	DATE	
HA7-5137A-5	1-Oct-10	1-Apr-11	1-Oct-11	NONE
HA9P2556-9	1-Oct-10	1-Apr-11	1-Oct-11	HA9P2556-9Z
HA9P2625-9	1-Oct-10	1-Apr-11	1-Oct-11	HA9P2525-5Z, HA9P2556-9Z
HA9P4905-5	1-Oct-10	1-Apr-11	1-Oct-11	HA9P4905-5Z
HA9P5002-5	1-Oct-10	1-Apr-11	1-Oct-11	HA9P5002-5Z
HA9P5002-9	1-Oct-10	1-Apr-11	1-Oct-11	HA9P5002-9Z
HA9P5104-9	1-Oct-10	1-Apr-11	1-Oct-11	HA9P5002-9Z, HA9P5127-5Z
HA9P5127-5	1-Oct-10	1-Apr-11	1-Oct-11	HA9P5127-5Z
HA9P5320-5	1-Oct-10	1-Apr-11	1-Oct-11	HA9P5320-5Z
HC55184ECM96R4749	1-Oct-10	1-Apr-11	1-Oct-11	HC55184ECMZ96
HC55185AIM	1-Oct-10	1-Apr-11	1-Oct-11	HC55185AIMZ
HC55185AIM96	1-Oct-10	1-Apr-11	1-Oct-11	HC55185AIMZ96
HC55185CIM	1-Oct-10	1-Apr-11	1-Oct-11	HC55185CIMZ
HC55185DIM	1-Oct-10	1-Apr-11	1-Oct-11	HC55185DIMZ
HC55185DIM96	1-Oct-10	1-Apr-11	1-Oct-11	HC55185DIMZ96
HC55185ECM96	1-Oct-10	1-Apr-11	1-Oct-11	HC55185ECMZ96
HC55185GCM	1-Oct-10	1-Apr-11	1-Oct-11	HC55185GCMZ
HC55185GCR96	1-Oct-10	1-Apr-11	1-Oct-11	HC55185GCRZ96
HC9P5504B-5	1-Oct-10	1-Apr-11	1-Oct-11	HC9P5504B-5Z
HC9P5504B-5X96	1-Oct-10	1-Apr-11	1-Oct-11	HC9P5504B-5ZX96
HFA1100IB	1-Oct-10	1-Apr-11	1-Oct-11	HFA1100IBZ
HFA1100IP	1-Oct-10	1-Apr-11	1-Oct-11	HFA1100IBZ
HFA1105IB	1-Oct-10	1-Apr-11	1-Oct-11	HFA1105IBZ
HFA1105IB96	1-Oct-10	1-Apr-11	1-Oct-11	HFA1105IBZ96
HFA1110IB	1-Oct-10	1-Apr-11	1-Oct-11	HFA1110IBZ
HFA1112IB	1-Oct-10	1-Apr-11	1-Oct-11	HFA1112IBZ
HFA1112IP	1-Oct-10	1-Apr-11	1-Oct-11	HFA1112IPZ
HFA1113IB	1-Oct-10	1-Apr-11	1-Oct-11	HFA1113IBZ
HFA1130IB	1-Oct-10	1-Apr-11	1-Oct-11	HFA1130IBZ
HFA1135IB	1-Oct-10	1-Apr-11	1-Oct-11	HFA1135IBZ
HFA1135IB96	1-Oct-10	1-Apr-11	1-Oct-11	HFA1135IBZ96
HFA1145IB	1-Oct-10	1-Apr-11	1-Oct-11	HFA1145IBZ
HFA1145IP	1-Oct-10	1-Apr-11	1-Oct-11	HFA1145IPZ
HFA1405IB	1-Oct-10	1-Apr-11	1-Oct-11	NONE
HFA1412IB	1-Oct-10	1-Apr-11	1-Oct-11	HFA1412IBZ
HFA3046B	1-Oct-10	1-Apr-11	1-Oct-11	HFA3046BZ
HFA3046B96	1-Oct-10	1-Apr-11	1-Oct-11	HFA3046BZ96
HFA3096B	1-Oct-10	1-Apr-11	1-Oct-11	HFA3096BZ
HFA3096B96	1-Oct-10	1-Apr-11	1-Oct-11	HFA3096BZ96
HFA3101B	1-Oct-10	1-Apr-11	1-Oct-11	HFA3101BZ
HFA3101B96	1-Oct-10	1-Apr-11	1-Oct-11	HFA3101BZ96
HFA3127B	1-Oct-10	1-Apr-11	1-Oct-11	HFA3127BZ

Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB /	SHIP/	Similar/
being impacted.	Date	WTHD	OBSOLETE	Re-Design
		DATE	DATE	
HFA3127B96	1-Oct-10	1-Apr-11	1-Oct-11	HFA3127BZ96
HFA3128B	1-Oct-10	1-Apr-11	1-Oct-11	HFA3128BZ
HI1-0201-4	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0201-5Z
HI1-0201-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0201-5Z
HI1-0201HS-4	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0201HS-5Z
HI1-0201HS-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0201HS-5Z
HI1-0303-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0303-5Z
HI1-0506-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0506A-5Z
HI1-0506A-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0506A-5Z
HI1-0506AB4306-002	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0506A-5Z
HI1-0506B4306-001	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0506A-5Z
HI1-0508-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0508-5Z
HI1-0509-4	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0509A-5Z
HI1-0509-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0509A-5Z
HI1-0509A-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0509A-5Z
HI1-0539-5	1-Oct-10	1-Apr-11	1-Oct-11	NONE
HI1-0546-5	1-Oct-10	1-Apr-11	1-Oct-11	HI4P0546-5Z
HI1-0547-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0547-5Z
HI1-0548-5	1-Oct-10	1-Apr-11	1-Oct-11	HI9P0548-5Z
HI1-5043-5	1-Oct-10	1-Apr-11	1-Oct-11	Hi3-5043-5Z
HI1-5047-5	1-Oct-10	1-Apr-11	1-Oct-11	NONE
HI1-5049-5	1-Oct-10	1-Apr-11	1-Oct-11	NONE
HI1-5051-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-5051-5Z
HI3-0201-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0201-5Z
HI3-0201HS-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0201HS-5Z
HI3-0303-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0303-5Z
HI3-0506A-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0506A-5Z
HI3-0507-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0507-5Z
HI3-0507A-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0507A-5Z
HI3-0508-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0508-5Z
HI3-0508A-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0508A-5Z
HI3-0509-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0509A-5Z
HI3-0509A-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0509A-5Z
HI3-0516-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0516-5Z
HI3-0518-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0518-5Z
HI3-0546-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0506A-5Z
HI3-0547-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0547-5Z
HI3-0548-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0508A-5Z
HI3-0549-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0509A-5Z
HI3338KIB	1-Oct-10	1-Apr-11	1-Oct-11	HI3338KIBZ
HI3-5043-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-5043-5Z
HI3-5051-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-5051-5Z
HI3-574AJN-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-574AJN-5Z
HI3-574AKN-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-574AKN-5Z

Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB /	SHIP/	Similar/
being impacted.	Date	WTHD	OBSOLETE	Re-Design
		DATE	DATE	
HI3-674AJN-5	1-Oct-10	1-Apr-11	1-Oct-11	NONE
HI3-674AKN-5	1-Oct-10	1-Apr-11	1-Oct-11	NONE
HI3-DAC80V-5	1-Oct-10	1-Apr-11	1-Oct-11	NONE
HI4P0506-5	1-Oct-10	1-Apr-11	1-Oct-11	HI4P0506-5Z
HI4P0509-5	1-Oct-10	1-Apr-11	1-Oct-11	HI4P0509-5Z
HI4P0546-5	1-Oct-10	1-Apr-11	1-Oct-11	HI4P0546-5Z
HI4P0547-5	1-Oct-10	1-Apr-11	1-Oct-11	HI4P0547-5Z
HI4P0548-5	1-Oct-10	1-Apr-11	1-Oct-11	HI3-0508A-5Z
HI5628/6IN	1-Oct-10	1-Apr-11	1-Oct-11	HI5628/6INZ
HI5628/6IN-T	1-Oct-10	1-Apr-11	1-Oct-11	HI5628/6INZ
HI5660/6IA	1-Oct-10	1-Apr-11	1-Oct-11	HI5660/6IAZ
HI5660/6IA-T	1-Oct-10	1-Apr-11	1-Oct-11	HI5660/6IAZ-T
HI5714/7CB	1-Oct-10	1-Apr-11	1-Oct-11	HI5714/7CBZ-T
HI5728/6IN	1-Oct-10	1-Apr-11	1-Oct-11	HI5728/6INZ
HI5728IN	1-Oct-10	1-Apr-11	1-Oct-11	HI5728INZ
HI5728IN-T	1-Oct-10	1-Apr-11	1-Oct-11	HI5728INZ-T
HI5731BIB	1-Oct-10	1-Apr-11	1-Oct-11	HI5731BIBZ
HI5731BIP	1-Oct-10	1-Apr-11	1-Oct-11	HI5731BIPZ
HI5735KCB	1-Oct-10	1-Apr-11	1-Oct-11	HI5735KCBZ
HI5741BIB	1-Oct-10	1-Apr-11	1-Oct-11	HI5741BIBZ
HI5746KCB	1-Oct-10	1-Apr-11	1-Oct-11	HI5746KCBZ
HI5760IA	1-Oct-10	1-Apr-11	1-Oct-11	HI5760IAZ
HI5762/6IN	1-Oct-10	1-Apr-11	1-Oct-11	HI5762/6INZ
HI5812JIB	1-Oct-10	1-Apr-11	1-Oct-11	HI5812JIBZ
HI5812JIP	1-Oct-10	1-Apr-11	1-Oct-11	HI5812JIPZ
HI5812KIB	1-Oct-10	1-Apr-11	1-Oct-11	HI5812KIBZ
HI5828IN	1-Oct-10	1-Apr-11	1-Oct-11	HI5828INZ
HI5960IB	1-Oct-10	1-Apr-11	1-Oct-11	HI5960IBZ
HI7188IN	1-Oct-10	1-Apr-11	1-Oct-11	HI7188WR5345
HI7190IB	1-Oct-10	1-Apr-11	1-Oct-11	HI7190IBZ
HI7190IP	1-Oct-10	1-Apr-11	1-Oct-11	HI7190IPZ
HI7191IB	1-Oct-10	1-Apr-11	1-Oct-11	HI7191IBZ
HI7191IP	1-Oct-10	1-Apr-11	1-Oct-11	HI7191IPZ
HI9P0201-5	1-Oct-10	1-Apr-11	1-Oct-11	HI9P0201-5Z
HI9P0201-9	1-Oct-10	1-Apr-11	1-Oct-11	HI9P0201-9Z
HI9P0201HS-5	1-Oct-10	1-Apr-11	1-Oct-11	HI9P0201HS-5Z
HI9P0201HS-9	1-Oct-10	1-Apr-11	1-Oct-11	HI9P0201HS-9Z
HI9P0303-9	1-Oct-10	1-Apr-11	1-Oct-11	HI9P0303-9Z
HI9P0506-9	1-Oct-10	1-Apr-11	1-Oct-11	HI9P0506-9Z
HI9P0508-5	1-Oct-10	1-Apr-11	1-Oct-11	HI9P0508-5Z
HI9P0508-9	1-Oct-10	1-Apr-11	1-Oct-11	HI9P0508-9Z
HI9P0509-5	1-Oct-10	1-Apr-11	1-Oct-11	HI9P0509-5Z
HI9P0546-9	1-Oct-10	1-Apr-11	1-Oct-11	HI9P0546-9Z
HI9P0547-9	1-Oct-10	1-Apr-11	1-Oct-11	HI9P0547-9Z



Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB /	SHIP/	Similar/
being impacted.	Date	WTHD	OBSOLETE	Re-Design
		DATE	DATE	
HI9P0548-5	1-Oct-10	1-Apr-11	1-Oct-11	HI9P0548-5Z
HI9P0548-9	1-Oct-10	1-Apr-11	1-Oct-11	HI9P0548-9Z
HI9P0549-9	1-Oct-10	1-Apr-11	1-Oct-11	HI9P0549-9Z
HI9P5043-5	1-Oct-10	1-Apr-11	1-Oct-11	HI9P5043-5Z
HI9P5051-9	1-Oct-10	1-Apr-11	1-Oct-11	HI9P5051-9Z
HIN202CB	1-Oct-10	1-Apr-11	1-Oct-11	HIN202CBZ
HIN202CBN	1-Oct-10	1-Apr-11	1-Oct-11	HIN202CBNZ
HIN202CBN-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN202CBNZ-T
HIN202CB-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN202CBZ-T
HIN202CP	1-Oct-10	1-Apr-11	1-Oct-11	HIN202CPZ
HIN202ECB	1-Oct-10	1-Apr-11	1-Oct-11	HIN202ECBZ
HIN202ECBN	1-Oct-10	1-Apr-11	1-Oct-11	HIN202ECBNZ
HIN202ECBN-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN202ECBNZ-T
HIN202ECP	1-Oct-10	1-Apr-11	1-Oct-11	HIN202ECPZ
HIN202EIB	1-Oct-10	1-Apr-11	1-Oct-11	HIN202EIBZ
HIN202EIBN	1-Oct-10	1-Apr-11	1-Oct-11	HIN202EIBNZ
HIN202EIBN-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN202EIBNZ-T
HIN202EIB-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN202EIBZ-T
HIN202IB	1-Oct-10	1-Apr-11	1-Oct-11	HIN202IBZ
HIN202IBN	1-Oct-10	1-Apr-11	1-Oct-11	HIN202IBNZ
HIN202IBN-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN202IBNZ-T
HIN206CB	1-Oct-10	1-Apr-11	1-Oct-11	HIN206ECBZ
HIN206ECB-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN206ECBZ-T
HIN207ECA-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN207ECAZ-T
HIN207EIB-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN207EIBZ-T
HIN208ECA-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN208ECAZ-T
HIN208ECB	1-Oct-10	1-Apr-11	1-Oct-11	HIN208ECBZ
HIN208ECB-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN208ECBZ-T
HIN208EIA	1-Oct-10	1-Apr-11	1-Oct-11	HIN208EIAZ
HIN208EIA-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN208EIAZ-T
HIN211CA	1-Oct-10	1-Apr-11	1-Oct-11	HIN211CAZ
HIN211CA-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN211CAZ-T
HIN211CB-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN211CBZ-T
HIN211ECA	1-Oct-10	1-Apr-11	1-Oct-11	HIN211ECAZ
HIN211ECA-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN211ECAZ-T
HIN211EIA	1-Oct-10	1-Apr-11	1-Oct-11	HIN211EIAZ
HIN211EIA-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN211EIAZ-T
HIN211EIB	1-Oct-10	1-Apr-11	1-Oct-11	HIN211EIBZ
HIN213CA-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN213CAZ-T
HIN213EIA	1-Oct-10	1-Apr-11	1-Oct-11	HIN213EIAZ
HIN213EIA-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN213EIAZ-T
HIN213EIB	1-Oct-10	1-Apr-11	1-Oct-11	HIN213EIBZ
HIN232ACB	1-Oct-10	1-Apr-11	1-Oct-11	HIN232ACBZ
HIN232ACBN	1-Oct-10	1-Apr-11	1-Oct-11	HIN232ACBNZ

Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB /	SHIP/	Similar/
being impacted.	Date	WTHD	OBSOLETE	Re-Design
		DATE	DATE	
HIN232ACBN-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN232ACBNZ-T
HIN232ACB-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN232ACBZ-T
HIN232ACP	1-Oct-10	1-Apr-11	1-Oct-11	HIN232ACPZ
HIN232CB	1-Oct-10	1-Apr-11	1-Oct-11	HIN232CBZ
HIN232CB-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN232CBZ-T
HIN232CP	1-Oct-10	1-Apr-11	1-Oct-11	HIN232CPZ
HIN232ECP	1-Oct-10	1-Apr-11	1-Oct-11	HIN232ECPZ
HIN232IB-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN232IBZ-T
HIN238CB	1-Oct-10	1-Apr-11	1-Oct-11	HIN238CBZ
HIN238IB	1-Oct-10	1-Apr-11	1-Oct-11	HIN238IBZ
HIN238IB-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN238IBZ-T
HIN239CB	1-Oct-10	1-Apr-11	1-Oct-11	HIN239CBZ
HIN239CB-T	1-Oct-10	1-Apr-11	1-Oct-11	HIN239CBZ-T
HIN240CN	1-Oct-10	1-Apr-11	1-Oct-11	HIN240CNZ
ICL232CBE	1-Oct-10	1-Apr-11	1-Oct-11	ICL232CBEZ
ICL232CPE	1-Oct-10	1-Apr-11	1-Oct-11	ICL232CBEZ
ICL232IBE	1-Oct-10	1-Apr-11	1-Oct-11	NONE
ICL232IBET	1-Oct-10	1-Apr-11	1-Oct-11	NONE
ICL232IPE	1-Oct-10	1-Apr-11	1-Oct-11	NONE
ICL232MJE	1-Oct-10	1-Apr-11	1-Oct-11	HIN232IPZ
ICL3207CB	1-Oct-10	1-Apr-11	1-Oct-11	ICL3207CBZ
ICL3207ECA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3207ECAZ-T
ICL3207IA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3207IAZ-T
ICL3217IB	1-Oct-10	1-Apr-11	1-Oct-11	ICL3217IBZ
ICL3221CA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3221CAZ
ICL3221CA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3221CAZ-T
ICL3221CV	1-Oct-10	1-Apr-11	1-Oct-11	ICL3221CVZ
ICL3221ECA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3221ECAZ
ICL3221ECA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3221ECAZ-T
ICL3221ECV	1-Oct-10	1-Apr-11	1-Oct-11	ICL3221ECVZ
ICL3221EIA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3221EIAZ
ICL3221EIA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3221EIAZ-T
ICL3221IA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3221IAZ
ICL3221IA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3221IAZ-T
ICL3222ECA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3222ECAZ-T
ICL3222ECP	1-Oct-10	1-Apr-11	1-Oct-11	NONE
ICL3222EIB	1-Oct-10	1-Apr-11	1-Oct-11	ICL3222EIBZ
ICL3222EIB-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3222EIBZ-T
ICL3222EIV-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3222EIVZ-T
ICL3222IV	1-Oct-10	1-Apr-11	1-Oct-11	ICL3222IVZ
ICL3222IV-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3222IVZ-T
ICL3223CA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3223CAZ
ICL3223CA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3223CAZ-T
ICL3223ECA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3223ECAZ

Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB / WTHD	SHIP/ OBSOLETE	Similar/
being impacted.	Date	DATE	DATE	Re-Design
ICL3223ECA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3223ECAZ-T
ICL3223ECV	1-Oct-10	1-Apr-11	1-Oct-11	ICL3223ECVZ
ICL3223EIA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3223EIAZ
ICL3223EIA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3223EIAZ-T
ICL3223EIV	1-Oct-10	1-Apr-11	1-Oct-11	ICL3223EIVZ
ICL3223IA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3223IAZ
ICL3223IA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3223IAZ-T
ICL3224CA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3224CAZ
ICL3224EIA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3224EIAZ
ICL3224EIA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3224EIAZ-T
ICL3224IA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3224IAZ-T
ICL3225ECA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3225ECAZ
ICL3225EIA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3225EIAZ
ICL3225EIA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3225EIAZ-T
ICL3227EIA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3227EIAZA
ICL3227EIA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3227EIAZA-T
ICL3232CA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232CAZ
ICL3232CA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232CAZ-T
ICL3232CBN	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232CBNZ
ICL3232CBN-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232CBNZ-T
ICL3232CB-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232CBZ-T
ICL3232CP	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232CPZ
ICL3232CV	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232CVZ
ICL3232CV-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232CVZ-T
ICL3232ECA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232ECAZ
ICL3232ECA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232ECAZ-T
ICL3232ECBN	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232ECBNZ
ICL3232ECBN-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232ECBNZ-T
ICL3232ECV-16T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232ECV-16Z-T
ICL3232EIA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232EIAZ-T
ICL3232EIB-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232EIBZ-T
ICL3232EIV-16	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232EIV-16Z
ICL3232IBN	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232IBNZ
ICL3232IBN-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232IBNZ-T
ICL3232IB-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232IBZ-T
ICL3232IV	1-Oct-10	1-Apr-11	1-Oct-11	ICL3232IVZ
ICL3237CA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3237CAZ-T
ICL3237EIA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3237EIAZ
ICL3238CA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3238CAZ-T
ICL3238ECA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3238ECAZ
ICL3238EIA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3238EIAZ
ICL3238EIA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3238EIAZ-T
ICL3238IA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3238IAZ
ICL3241ECA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3241ECAZ

Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB /	SHIP/	Similar/
being impacted.	Date	WTHD	OBSOLETE	Re-Design
		DATE	DATE	
ICL3241ECA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3241ECAZ-T
ICL3241EIA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3241EIAZ-T
ICL3241EIA-TS2705	1-Oct-10	1-Apr-11	1-Oct-11	ICL3241EIAZ-TS2705
ICL3243CA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3243CAZ
ICL3243CA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3243CAZ-T
ICL3243CB	1-Oct-10	1-Apr-11	1-Oct-11	ICL3243CBZ
ICL3243ECA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3243ECAZ
ICL3243ECA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3243ECAZ-T
ICL3243ECV-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3243ECVZ-T
ICL3243EIA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3243EIAZ-T
ICL3243EIV	1-Oct-10	1-Apr-11	1-Oct-11	ICL3243EIVZ
ICL3244CA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3244ECAZ
ICL3244ECA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3244ECAZ-T
ICL3244ECA-TS2705	1-Oct-10	1-Apr-11	1-Oct-11	ICL3244ECAZ-TS2705
ICL3244EIB	1-Oct-10	1-Apr-11	1-Oct-11	ICL3244EIAZ
ICL3245CA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3245CAZ
ICL3245CA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3245CAZ-T
ICL3245ECA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3245ECAZ
ICL3245ECA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL3245ECAZ-T
ICL3245ECA-TS2705	1-Oct-10	1-Apr-11	1-Oct-11	ICL3245ECAZ-TS2705
ICL3245EIA	1-Oct-10	1-Apr-11	1-Oct-11	ICL3245EIAZ
ICL7106CM44	1-Oct-10	1-Apr-11	1-Oct-11	ICL7106CM44Z
ICL7106CPL	1-Oct-10	1-Apr-11	1-Oct-11	ICL7106CPLZ
ICL7107CM44	1-Oct-10	1-Apr-11	1-Oct-11	ICL7107CM44Z
ICL7107CM44T	1-Oct-10	1-Apr-11	1-Oct-11	ICL7107CM44ZT
ICL7107CPL	1-Oct-10	1-Apr-11	1-Oct-11	ICL7107CPLZ
ICL7107SCPL	1-Oct-10	1-Apr-11	1-Oct-11	ICL7107SCPLZ
ICL7126CPL	1-Oct-10	1-Apr-11	1-Oct-11	ICL7126CPLZ
ICL7135CPI	1-Oct-10	1-Apr-11	1-Oct-11	ICL7135CPIZ
ICL7136CM44	1-Oct-10	1-Apr-11	1-Oct-11	ICL7136CM44Z
ICL7136CPL	1-Oct-10	1-Apr-11	1-Oct-11	ICL7136CPLZ
ICL7611DCBA	1-Oct-10	1-Apr-11	1-Oct-11	ICL7611DCBAZ
ICL7611DCBA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL7611DCBAZ-T
ICL7611DCPA	1-Oct-10	1-Apr-11	1-Oct-11	ICL7611DCPAZ
ICL7612BCPA	1-Oct-10	1-Apr-11	1-Oct-11	ICL7612BCPAZ
ICL7612DCBA	1-Oct-10	1-Apr-11	1-Oct-11	ICL7612DCBAZ
ICL7612DCBA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL7612DCBAZ-T
ICL7612DCPA	1-Oct-10	1-Apr-11	1-Oct-11	ICL7612DCPAZ
ICL7621DCBA	1-Oct-10	1-Apr-11	1-Oct-11	ICL7621DCBAZ
ICL7621DCBA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICL7621DCBAZ-T
ICL7621DCPA	1-Oct-10	1-Apr-11	1-Oct-11	ICL7621DCPAZ
ICL7650SCBA-1	1-Oct-10	1-Apr-11	1-Oct-11	ICL7650SCBA-1Z
ICL7650SCPA-1	1-Oct-10	1-Apr-11	1-Oct-11	ICL7650SCPA-1Z
ICL7650SCPD	1-Oct-10	1-Apr-11	1-Oct-11	ICL7650SCPDZ

Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB /	SHIP/	Similar/
being impacted.	Date	WTHD	OBSOLETE	Re-Design
		DATE	DATE	
ICM7242IPA	1-Oct-10	1-Apr-11	1-Oct-11	ICM7242IPAZ
ICM7555CBA	1-Oct-10	1-Apr-11	1-Oct-11	ICM7555CBAZ
ICM7555CBA-T	1-Oct-10	1-Apr-11	1-Oct-11	ICM7555CBAZ-T
ICM7555IBA	1-Oct-10	1-Apr-11	1-Oct-11	ICM7555IBAZ
ICM7555IBAT	1-Oct-10	1-Apr-11	1-Oct-11	ICM7555IBAZ-T
ICM7555IPA	1-Oct-10	1-Apr-11	1-Oct-11	ICM7555IPAZ
ICM7556IPD	1-Oct-10	1-Apr-11	1-Oct-11	ICM7556IPDZ
ICM7556MJD	1-Oct-10	1-Apr-11	1-Oct-11	NONE
ISL1485R5171	1-Oct-10	1-Apr-11	1-Oct-11	NONE
ISL4221EIR	1-Oct-10	1-Apr-11	1-Oct-11	ISL4221EIRZ
ISL4223EIR	1-Oct-10	1-Apr-11	1-Oct-11	ISL4223EIRZ
ISL4223EIR-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL4223EIRZ-T
ISL4238EIR	1-Oct-10	1-Apr-11	1-Oct-11	ISL4238EIRZ
ISL4238EIR-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL4238EIRZ-T
ISL4243EIR	1-Oct-10	1-Apr-11	1-Oct-11	ISL4243EIRZ
ISL4244EIR	1-Oct-10	1-Apr-11	1-Oct-11	ISL4244EIRZ
ISL4244EIR-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL4244EIRZ-T
ISL4245EIR	1-Oct-10	1-Apr-11	1-Oct-11	ISL4245EIRZ
ISL43112IB	1-Oct-10	1-Apr-11	1-Oct-11	ISL43112IBZ
ISL43141IV-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL43141IVZ-T
ISL43144IR	1-Oct-10	1-Apr-11	1-Oct-11	ISL43144IRZ
ISL43144IR-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL43144IRZ-T
ISL43144IV	1-Oct-10	1-Apr-11	1-Oct-11	ISL43144IVZ
ISL43144IV-TR5172	1-Oct-10	1-Apr-11	1-Oct-11	ISL43144IVZ-TR5172
ISL43240IA	1-Oct-10	1-Apr-11	1-Oct-11	ISL43240IAZ
ISL43240IA-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL43240IAZ-T
ISL43240IR	1-Oct-10	1-Apr-11	1-Oct-11	ISL43240IRZ
ISL43640IR	1-Oct-10	1-Apr-11	1-Oct-11	ISL43640IRZ
ISL43681IR	1-Oct-10	1-Apr-11	1-Oct-11	ISL43681IRZ
ISL43L120IU	1-Oct-10	1-Apr-11	1-Oct-11	ISL43L120IUZ
ISL4485EIB	1-Oct-10	1-Apr-11	1-Oct-11	ISL4485EIBZ
ISL4486IB	1-Oct-10	1-Apr-11	1-Oct-11	ISL4486IBZ
ISL4486IB-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL4486IBZ-T
ISL4491EIB	1-Oct-10	1-Apr-11	1-Oct-11	ISL4491EIBZ
ISL55004IB	1-Oct-10	1-Apr-11	1-Oct-11	ISL55004IBZ
ISL5585FCM	1-Oct-10	1-Apr-11	1-Oct-11	ISL5585FCMZ
ISL5729/2IN	1-Oct-10	1-Apr-11	1-Oct-11	ISL5729/2INZ
ISL5729IN	1-Oct-10	1-Apr-11	1-Oct-11	ISL5729INZ
ISL5761/2IB	1-Oct-10	1-Apr-11	1-Oct-11	ISL5761/2IBZ
ISL5927IN	1-Oct-10	1-Apr-11	1-Oct-11	ISL5927INZ
ISL5929IN	1-Oct-10	1-Apr-11	1-Oct-11	ISL5929INZ
ISL60002DIH312-TK	1-Oct-10	1-Apr-11	1-Oct-11	ISL60002DIH312Z-TK
ISL81483IB	1-Oct-10	1-Apr-11	1-Oct-11	ISL81483IBZ
ISL81483IB-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL81483IBZ-T

Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB / WTHD	SHIP/ OBSOLETE	Similar/
being impacted.	Date	DATE	DATE	Re-Design
ISL81487EIP	1-Oct-10	1-Apr-11	1-Oct-11	ISL81487EIPZ
ISL81487LIB	1-Oct-10	1-Apr-11	1-Oct-11	ISL81487LIBZ
ISL81487LIB-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL81487LIBZ-T
ISL81487LIP	1-Oct-10	1-Apr-11	1-Oct-11	ISL81487LIPZ
ISL83080EIB	1-Oct-10	1-Apr-11	1-Oct-11	ISL83080EIBZ
ISL83085EIB-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL83085EIBZ-T
ISL83086EIB	1-Oct-10	1-Apr-11	1-Oct-11	ISL83086EIBZ
ISL83088EIB	1-Oct-10	1-Apr-11	1-Oct-11	ISL83088EIBZ
ISL8323IB	1-Oct-10	1-Apr-11	1-Oct-11	ISL8323IBZ
ISL83386EIV	1-Oct-10	1-Apr-11	1-Oct-11	ISL83386EIVZ
ISL83387EIV	1-Oct-10	1-Apr-11	1-Oct-11	ISL83387EIVZ
ISL83483IB	1-Oct-10	1-Apr-11	1-Oct-11	ISL83483IBZ
ISL83483IB-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL83483IBZ-T
ISL83485IB	1-Oct-10	1-Apr-11	1-Oct-11	ISL83485IBZ
ISL83485IP	1-Oct-10	1-Apr-11	1-Oct-11	ISL83485IBZ
ISL83488IB	1-Oct-10	1-Apr-11	1-Oct-11	ISL83488IBZ
ISL83488IB-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL83488IBZ-T
ISL83490IB	1-Oct-10	1-Apr-11	1-Oct-11	ISL83490IBZ
ISL83491IB	1-Oct-10	1-Apr-11	1-Oct-11	ISL83491IBZ
ISL83491IP	1-Oct-10	1-Apr-11	1-Oct-11	ISL83491IBZ
ISL8392IB	1-Oct-10	1-Apr-11	1-Oct-11	ISL8392IBZ
ISL84051IA	1-Oct-10	1-Apr-11	1-Oct-11	ISL84051IAZ
ISL84051IA-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL84051IAZ-T
ISL84051IB	1-Oct-10	1-Apr-11	1-Oct-11	ISL84051IBZ
ISL84051IB-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL84051IBZ-T
ISL84053IA-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL84053IAZ-T
ISL84522IB-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL84522IBZ-T
ISL84542CB	1-Oct-10	1-Apr-11	1-Oct-11	ISL84542CBZ
ISL84544IP	1-Oct-10	1-Apr-11	1-Oct-11	ISL84544IPZ
ISL8483EIB	1-Oct-10	1-Apr-11	1-Oct-11	ISL8483EIBZ
ISL8483EIB-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL8483EIBZ-T
ISL8483IB-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL8483IBZ-T
ISL8485EIB	1-Oct-10	1-Apr-11	1-Oct-11	ISL8485EIBZ
ISL8485EIP	1-Oct-10	1-Apr-11	1-Oct-11	ISL8485EIPZ
ISL8485IB-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL8485IBZ-T
ISL8487EIB	1-Oct-10	1-Apr-11	1-Oct-11	ISL8487EIBZ
ISL8488IB	1-Oct-10	1-Apr-11	1-Oct-11	ISL8488IBZ
ISL8489IB	1-Oct-10	1-Apr-11	1-Oct-11	ISL8489EIBZ
ISL8489IB-T	1-Oct-10	1-Apr-11	1-Oct-11	ISL8489EIBZ-T
ISL8489IP	1-Oct-10	1-Apr-11	1-Oct-11	ISL8489EIBZ
ISL8490IB	1-Oct-10	1-Apr-11	1-Oct-11	ISL8490IBZ
ISL8563ECB	1-Oct-10	1-Apr-11	1-Oct-11	NONE
X90100M8I	1-Oct-10	1-Apr-11	1-Oct-11	X90100M8IZ
X90100M8IT1	1-Oct-10	1-Apr-11	1-Oct-11	X90100M8IZT1

Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB /	SHIP/	Similar/
being impacted.	Date	WTHD	OBSOLETE	Re-Design
		DATE	DATE	
X9015US8	1-Oct-10	1-Apr-11	1-Oct-11	X9015US8Z
X9015US8-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9015US8Z-2.7
X9015US8-2.7T1	1-Oct-10	1-Apr-11	1-Oct-11	X9015US8Z-2.7T1
X9015US8I	1-Oct-10	1-Apr-11	1-Oct-11	X9015US8IZ
X9015US8I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9015US8IZ-2.7
X9015WS8-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9015WS8Z-2.7
X9110TV14	1-Oct-10	1-Apr-11	1-Oct-11	X9110TV14Z
X9110TV14I	1-Oct-10	1-Apr-11	1-Oct-11	X9110TV14IZ
X9111TV14	1-Oct-10	1-Apr-11	1-Oct-11	X9111TV14Z
X9111TV14-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9111TV14Z-2.7
X9116WS8I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9116WS8IZ-2.7
X9116WS8T2	1-Oct-10	1-Apr-11	1-Oct-11	NONE
X9118TV14	1-Oct-10	1-Apr-11	1-Oct-11	X9118TV14Z
X9119TV14	1-Oct-10	1-Apr-11	1-Oct-11	X9119TV14Z
X9119TV14-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9119TV14Z-2.7
X9119TV14I	1-Oct-10	1-Apr-11	1-Oct-11	X9119TV14IZ
X9119TV14I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9119TV14IZ-2.7
X9221AWS	1-Oct-10	1-Apr-11	1-Oct-11	X9221AWSZ
X9221AWSI	1-Oct-10	1-Apr-11	1-Oct-11	X9221AWSIZ
X9221AYP	1-Oct-10	1-Apr-11	1-Oct-11	X9221AYPZ
X9241AMP	1-Oct-10	1-Apr-11	1-Oct-11	X9241AMPZ
X9241AMS	1-Oct-10	1-Apr-11	1-Oct-11	X9241AMSZ
X9241AMSIT1	1-Oct-10	1-Apr-11	1-Oct-11	X9241AMSIZT1
X9241AMSIT1C7168	1-Oct-10	1-Apr-11	1-Oct-11	X9241AMSIZT1
X9241AUP	1-Oct-10	1-Apr-11	1-Oct-11	X9241AUPZ
X9241AUS	1-Oct-10	1-Apr-11	1-Oct-11	X9241AUSZ
X9241AUSI	1-Oct-10	1-Apr-11	1-Oct-11	X9241AUSIZ
X9241AUVIT1	1-Oct-10	1-Apr-11	1-Oct-11	X9241AUVIZT1
X9241AWP	1-Oct-10	1-Apr-11	1-Oct-11	X9241AWPIZ
X9241AWPI	1-Oct-10	1-Apr-11	1-Oct-11	X9241AWPIZ
X9241AWS	1-Oct-10	1-Apr-11	1-Oct-11	X9241AWSZ
X9241AWSI	1-Oct-10	1-Apr-11	1-Oct-11	X9241AWSIZ
X9241AWSIT1	1-Oct-10	1-Apr-11	1-Oct-11	X9241AWSIZT1
X9241AWST1	1-Oct-10	1-Apr-11	1-Oct-11	X9241AWSZT1
X9241AWVI	1-Oct-10	1-Apr-11	1-Oct-11	X9241AWVIZ
X9241AWVIT1	1-Oct-10	1-Apr-11	1-Oct-11	X9241AWVIZT1
X9241AWVIT2	1-Oct-10	1-Apr-11	1-Oct-11	NONE
X9241AWVT1	1-Oct-10	1-Apr-11	1-Oct-11	X9241AWVZT1
X9241AYP	1-Oct-10	1-Apr-11	1-Oct-11	X9241AYPZ
X9241AYS	1-Oct-10	1-Apr-11	1-Oct-11	X9241AYSZ
X9241AYSIT1C7975	1-Oct-10	1-Apr-11	1-Oct-11	X9241AYSIZT1
X9250TS24	1-Oct-10	1-Apr-11	1-Oct-11	X9250TS24Z
X9250TS24-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9250TS24Z-2.7
X9250TS24I	1-Oct-10	1-Apr-11	1-Oct-11	NONE

Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB / WTHD	SHIP/ OBSOLETE	Similar/
being impacted.	Date	DATE	DATE	Re-Design
X9250TS24I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9250TS24IZ-2.7
X9250TV24I	1-Oct-10	1-Apr-11	1-Oct-11	NONE
X9250US24	1-Oct-10	1-Apr-11	1-Oct-11	X9250US24Z
X9250US24I	1-Oct-10	1-Apr-11	1-Oct-11	NONE
X9250US24I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9250US24IZ-2.7
X9250UV24I	1-Oct-10	1-Apr-11	1-Oct-11	X9250UV24IZ
X9251TS24I	1-Oct-10	1-Apr-11	1-Oct-11	X9251TS24IZ
X9251TV24-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9251TV24Z-2.7
X9251US24	1-Oct-10	1-Apr-11	1-Oct-11	X9251US24Z
X9251UV24	1-Oct-10	1-Apr-11	1-Oct-11	X9251UV24Z
X9251UV24I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9251UV24IZ-2.7
X9252UV24I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9252UV24IZ-2.7
X9252WV24I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9252WV24IZ-2.7
X9252YV24I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9252YV24IZ-2.7
X9258TS24	1-Oct-10	1-Apr-11	1-Oct-11	X9258TS24Z
X9258TS24I	1-Oct-10	1-Apr-11	1-Oct-11	X9258TS24IZ
X9258TS24I-2.7T1	1-Oct-10	1-Apr-11	1-Oct-11	X9258TS24IZ-2.7T1
X9258TS24I-27T2C9056	1-Oct-10	1-Apr-11	1-Oct-11	X9258TS24IZ-2.7T1
X9258TV24I	1-Oct-10	1-Apr-11	1-Oct-11	NONE
X9258US24	1-Oct-10	1-Apr-11	1-Oct-11	X9258US24Z
X9258US24-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9258US24Z-2.7
X9258US24I-2.7T1	1-Oct-10	1-Apr-11	1-Oct-11	X9258US24IZ-2.7T1
X9258US24IT1	1-Oct-10	1-Apr-11	1-Oct-11	X9258US24IZT1
X9258UV24-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9258UV24IZ-2.7
X9258UV24-2.7T1	1-Oct-10	1-Apr-11	1-Oct-11	X9258UV24IZ-2.7
X9258UV24I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9258UV24IZ-2.7
X9259TS24	1-Oct-10	1-Apr-11	1-Oct-11	X9259TS24Z
X9259UV24-2.7T1	1-Oct-10	1-Apr-11	1-Oct-11	X9259UV24IZ-2.7T1
X9259UV24I	1-Oct-10	1-Apr-11	1-Oct-11	X9259UV24IZ
X9259UV24I-2.7T1	1-Oct-10	1-Apr-11	1-Oct-11	X9259UV24IZ-2.7T1
X9261US24	1-Oct-10	1-Apr-11	1-Oct-11	X9261US24Z
X9261UV24	1-Oct-10	1-Apr-11	1-Oct-11	NONE
X9261UV24I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	NONE
X9268TS24	1-Oct-10	1-Apr-11	1-Oct-11	X9268TS24Z
X9268TS24T1	1-Oct-10	1-Apr-11	1-Oct-11	X9268TS24ZT1
X9268US24T1	1-Oct-10	1-Apr-11	1-Oct-11	X9268US24ZT1
X9269US24-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9269US24Z-2.7
X9269US24-2.7T1	1-Oct-10	1-Apr-11	1-Oct-11	X9269US24Z-2.7T1
X9271TV14	1-Oct-10	1-Apr-11	1-Oct-11	X9271TV14Z
X9271TV14I-2.7T1	1-Oct-10	1-Apr-11	1-Oct-11	X9271TV14IZ-2.7T1
X9271UV14I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9271UV14IZ-2.7
X9279UV14	1-Oct-10	1-Apr-11	1-Oct-11	X9279UV14Z
X9313UP	1-Oct-10	1-Apr-11	1-Oct-11	X9313UPZ
X9313US	1-Oct-10	1-Apr-11	1-Oct-11	X9313USZ



Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB /	SHIP/	Similar/
being impacted.	Date	WTHD	OBSOLETE	Re-Design
		DATE	DATE	
X9313US-3T2	1-Oct-10	1-Apr-11	1-Oct-11	X9313USZ-3T1
X9313USI-3C7711	1-Oct-10	1-Apr-11	1-Oct-11	X9313USIZ
X9313WP	1-Oct-10	1-Apr-11	1-Oct-11	X9313WPIZ
X9313WPI	1-Oct-10	1-Apr-11	1-Oct-11	X9313WPIZ
X9313WS	1-Oct-10	1-Apr-11	1-Oct-11	X9313WSZ
X9313WS-3	1-Oct-10	1-Apr-11	1-Oct-11	X9313WSZ-3
X9313WS-3T1	1-Oct-10	1-Apr-11	1-Oct-11	X9313WSZ-3T1
X9313WSC7576	1-Oct-10	1-Apr-11	1-Oct-11	X9313WSIZ
X9313WSI	1-Oct-10	1-Apr-11	1-Oct-11	X9313WSIZ
X9313WST1	1-Oct-10	1-Apr-11	1-Oct-11	X9313WSZT1
X9313WST2	1-Oct-10	1-Apr-11	1-Oct-11	X9313WSZT1
X9313ZM-3T1	1-Oct-10	1-Apr-11	1-Oct-11	X9313ZMZ-3T1
X9313ZP	1-Oct-10	1-Apr-11	1-Oct-11	X9313ZPIZ
X9313ZP-3	1-Oct-10	1-Apr-11	1-Oct-11	X9313ZPZ-3
X9313ZS	1-Oct-10	1-Apr-11	1-Oct-11	X9313ZSZ
X9313ZS-3	1-Oct-10	1-Apr-11	1-Oct-11	X9313ZSZ-3
X9313ZSI	1-Oct-10	1-Apr-11	1-Oct-11	X9313ZSIZ
X9313ZSI-3T1	1-Oct-10	1-Apr-11	1-Oct-11	X9313ZSIZ-3T1
X9313ZSIT1	1-Oct-10	1-Apr-11	1-Oct-11	X9313ZSIZT1
X9313ZST1	1-Oct-10	1-Apr-11	1-Oct-11	X9313ZSZT1
X9313ZST2	1-Oct-10	1-Apr-11	1-Oct-11	X9313ZSZT1
X9314WP	1-Oct-10	1-Apr-11	1-Oct-11	X9314WSZ
X9314WS	1-Oct-10	1-Apr-11	1-Oct-11	X9314WSZ
X9314WSI	1-Oct-10	1-Apr-11	1-Oct-11	X9314WSIZ
X9314WST1	1-Oct-10	1-Apr-11	1-Oct-11	X9314WSZT1
X93156UM8I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X93156UM8IZ-2.7
X9315TMI-2.7T1	1-Oct-10	1-Apr-11	1-Oct-11	X9315TMIZ-2.7T1
X9315UMIT2C7898	1-Oct-10	1-Apr-11	1-Oct-11	X9315UMIZ
X9315US-2.7T2	1-Oct-10	1-Apr-11	1-Oct-11	X9315USZ-2.7T1
X9315USI-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9315USIZ-2.7
X9315UST2	1-Oct-10	1-Apr-11	1-Oct-11	X9315USZT1
X9315WMI-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9315WMIZ-2.7
X9315WMI-2.7T1	1-Oct-10	1-Apr-11	1-Oct-11	X9315WMIZ-2.7T1
X9315WMI-2.7T2	1-Oct-10	1-Apr-11	1-Oct-11	X9315WMIZ-2.7T1
X9315WP	1-Oct-10	1-Apr-11	1-Oct-11	X9315WSZ
X9315WS	1-Oct-10	1-Apr-11	1-Oct-11	X9315WSZ
X9315WS-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9315WSZ-2.7
X9315WS-2.7T1	1-Oct-10	1-Apr-11	1-Oct-11	X9315WSZ-2.7T1
X9315WSI	1-Oct-10	1-Apr-11	1-Oct-11	X9315WSIZ
X9315WSI-2.7T1	1-Oct-10	1-Apr-11	1-Oct-11	X9315WSIZ-2.7T1
X9315WSIT1	1-Oct-10	1-Apr-11	1-Oct-11	X9315WSIZT1
X9315WSIT2C7898	1-Oct-10	1-Apr-11	1-Oct-11	X9315WSIZT1
X9317UM8I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9317UM8IZ-2.7
X9317US8I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9317US8IZ-2.7

Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB /	SHIP/	Similar/
being impacted.	Date	WTHD	OBSOLETE	Re-Design
		DATE	DATE	
X9317US8I-2.7T1	1-Oct-10	1-Apr-11	1-Oct-11	X9317US8IZ-2.7T1
X9317US8IT1	1-Oct-10	1-Apr-11	1-Oct-11	X9317US8IZT1
X9317WM8	1-Oct-10	1-Apr-11	1-Oct-11	X9317WM8Z
X9317WM8I	1-Oct-10	1-Apr-11	1-Oct-11	X9317WM8IZ
X9317WM8I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9317WM8IZ-2.7
X9317WM8IT1	1-Oct-10	1-Apr-11	1-Oct-11	X9317WM8IZT1
X9317WP	1-Oct-10	1-Apr-11	1-Oct-11	X9317WS8Z
X9317WS8	1-Oct-10	1-Apr-11	1-Oct-11	X9317WS8Z
X9317WS8-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9317WS8Z-2.7
X9317WS8I	1-Oct-10	1-Apr-11	1-Oct-11	X9317WS8IZ
X9317WS8I-2.7T1	1-Oct-10	1-Apr-11	1-Oct-11	X9317WS8IZ-2.7T1
X9317WS8T1	1-Oct-10	1-Apr-11	1-Oct-11	X9317WS8ZT1
X9317WV8	1-Oct-10	1-Apr-11	1-Oct-11	X9317WV8Z
X9317WV8I	1-Oct-10	1-Apr-11	1-Oct-11	X9317WV8IZ
X9319WS8I	1-Oct-10	1-Apr-11	1-Oct-11	X9319WS8IZ
X9400WS24I	1-Oct-10	1-Apr-11	1-Oct-11	X9400WS24IZ
X9400WS24I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9400WS24IZ-2.7
X9400WS24I-2.7T1	1-Oct-10	1-Apr-11	1-Oct-11	X9400WS24IZ-2.7T1
X9400WV24I	1-Oct-10	1-Apr-11	1-Oct-11	X9400WV24IZ
X9408WS24I	1-Oct-10	1-Apr-11	1-Oct-11	X9408WS24IZ-2.7
X9408WV24	1-Oct-10	1-Apr-11	1-Oct-11	X9408WV24Z
X9408WV24I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9408WV24IZ-2.7
X9408WV24I-2.7T1	1-Oct-10	1-Apr-11	1-Oct-11	X9408WV24IZ-2.7T1
X9408WV24I-2.7T2	1-Oct-10	1-Apr-11	1-Oct-11	X9408WV24IZ-2.7T1
X9408WV24T1	1-Oct-10	1-Apr-11	1-Oct-11	X9408WV24ZT1
X9408YS24	1-Oct-10	1-Apr-11	1-Oct-11	NONE
X9410WV24I	1-Oct-10	1-Apr-11	1-Oct-11	X9410WV24IZ
X9418WS24I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9418WS24IZ-2.7
X9418YS24-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9418YS24Z-2.7
X9420WS16	1-Oct-10	1-Apr-11	1-Oct-11	X9420WS16Z
X9420WV14I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X9420WV14IZ-2.7
X9420YS16I	1-Oct-10	1-Apr-11	1-Oct-11	X9420YS16IZ
X9421WV14I-2.7T1	1-Oct-10	1-Apr-11	1-Oct-11	X9421WV14IZ-2.7T1
X9428WS16	1-Oct-10	1-Apr-11	1-Oct-11	X9428WS16Z
X9429WV14I	1-Oct-10	1-Apr-11	1-Oct-11	X9429WV14IZ
X9429WV14I-2.7T2	1-Oct-10	1-Apr-11	1-Oct-11	X9429WV14IZ-2.7T1
X9455TV24IZ-2.7	1-Oct-10	29-Oct-10	1-Feb-11	X9252TV24IZ-2.7
X9455US24IZ-2.7	1-Oct-10	29-Oct-10	1-Feb-11	X9252US24IZ-2.7
X9455UV24IZ-2.7	1-Oct-10	29-Oct-10	1-Feb-11	X9252UV24IZ-2.7
X9455WS24IZ-2.7	1-Oct-10	29-Oct-10	1-Feb-11	X9252WS24IZ-2.7
X9455WV24IZ-2.7	1-Oct-10	29-Oct-10	1-Feb-11	X9252WV24IZ-2.7
X9455YS24IZ-2.7	1-Oct-10	29-Oct-10	1-Feb-11	X9252YS24IZ-2.7
X9455YV24IZ-2.7	1-Oct-10	29-Oct-10	1-Feb-11	X9252YV24IZ-2.7
X9511WP	1-Oct-10	1-Apr-11	1-Oct-11	X9511WPZ

Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB /	SHIP/	Similar/
being impacted.	Date	WTHD	OBSOLETE	Re-Design
		DATE	DATE	
X9511WPI	1-Oct-10	1-Apr-11	1-Oct-11	X9511WPIZ
X9511WS	1-Oct-10	1-Apr-11	1-Oct-11	X9511WSZ
X9511WSI	1-Oct-10	1-Apr-11	1-Oct-11	X9511WSIZ
X9511WSIT1	1-Oct-10	1-Apr-11	1-Oct-11	X9511WSIZT1
X9511WST1	1-Oct-10	1-Apr-11	1-Oct-11	X9511WSZT1
X9511WST2	1-Oct-10	1-Apr-11	1-Oct-11	X9511WSZT1
X9530V14I	1-Oct-10	1-Apr-11	1-Oct-11	X9530V14IZ
X95820UV14I-2.7	1-Oct-10	1-Apr-11	1-Oct-11	X95820UV14IZ-2.7
X96010V14I	1-Oct-10	1-Apr-11	1-Oct-11	X96010V14IZ
X96012V14I	1-Oct-10	1-Apr-11	1-Oct-11	X96012V14IZ
X98017L128-3.3	1-Oct-10	1-Apr-11	1-Oct-11	X98017L128-3.3-Z
X9C102P	1-Oct-10	1-Apr-11	1-Oct-11	X9C102PZ
X9C102PI	1-Oct-10	1-Apr-11	1-Oct-11	X9C102PIZ
X9C102S	1-Oct-10	1-Apr-11	1-Oct-11	X9C102SZ
X9C102SI	1-Oct-10	1-Apr-11	1-Oct-11	X9C102SIZ
X9C102SIT1	1-Oct-10	1-Apr-11	1-Oct-11	X9C102SIZT1
X9C102ST1	1-Oct-10	1-Apr-11	1-Oct-11	X9C102SZT1
X9C102ST2	1-Oct-10	1-Apr-11	1-Oct-11	X9C102SZT1
X9C103P	1-Oct-10	1-Apr-11	1-Oct-11	X9C103PZ
X9C103PI	1-Oct-10	1-Apr-11	1-Oct-11	X9C103PIZ
X9C103PIC7644	1-Oct-10	1-Apr-11	1-Oct-11	X9C103PIZ
X9C103S	1-Oct-10	1-Apr-11	1-Oct-11	X9C103SZ
X9C103SI	1-Oct-10	1-Apr-11	1-Oct-11	X9C103SIZ
X9C103SIT1	1-Oct-10	1-Apr-11	1-Oct-11	X9C103SIZT1
X9C103SIT2	1-Oct-10	1-Apr-11	1-Oct-11	X9C103SIZT2
X9C103ST1	1-Oct-10	1-Apr-11	1-Oct-11	X9C103SZT1
X9C103ST2	1-Oct-10	1-Apr-11	1-Oct-11	X9C103SZT2
X9C104P	1-Oct-10	1-Apr-11	1-Oct-11	X9C104PIZ
X9C104PI	1-Oct-10	1-Apr-11	1-Oct-11	X9C104PIZ
X9C104S	1-Oct-10	1-Apr-11	1-Oct-11	X9C104SZ
X9C104SI	1-Oct-10	1-Apr-11	1-Oct-11	X9C104SIZ
X9C104SIT1	1-Oct-10	1-Apr-11	1-Oct-11	X9C104SIZT1
X9C104SIT2	1-Oct-10	1-Apr-11	1-Oct-11	X9C104SIZT1
X9C104ST1	1-Oct-10	1-Apr-11	1-Oct-11	X9C104SZT1
X9C303P	1-Oct-10	1-Apr-11	1-Oct-11	X9C303PZ
X9C303PI	1-Oct-10	1-Apr-11	1-Oct-11	X9C303PIZ
X9C303S8I	1-Oct-10	1-Apr-11	1-Oct-11	X9C303S8IZ
X9C303V8	1-Oct-10	1-Apr-11	1-Oct-11	X9C303V8Z
X9C303V8T1	1-Oct-10	1-Apr-11	1-Oct-11	X9C303V8ZT1
X9C503P	1-Oct-10	1-Apr-11	1-Oct-11	X9C503PZ
X9C503PI	1-Oct-10	1-Apr-11	1-Oct-11	X9C503PIZ
X9C503S	1-Oct-10	1-Apr-11	1-Oct-11	X9C503SZ
X9C503SI	1-Oct-10	1-Apr-11	1-Oct-11	X9C503SIZ
X9C503SIT1	1-Oct-10	1-Apr-11	1-Oct-11	X9C503SIZT1

Exact Intersil Part #	Notice			Replacement/
No other variation is	PLC10100	LTB / WTHD	SHIP/ OBSOLETE	Similar/
being impacted.	Date	DATE	DATE	Re-Design
X9C503SIT1C7884	1-Oct-10	1-Apr-11	1-Oct-11	X9C503SIZT1
X9C503SIT2C7928	1-Oct-10	1-Apr-11	1-Oct-11	X9C503SIZT1
X9C503ST1	1-Oct-10	1-Apr-11	1-Oct-11	X9C503SZT1