
[Upgrade to Revision]

R20TS1043EJ0100

Rev.1.00

Jul. 20, 2024

e² studio RX Smart Configurator Plug-in 2024-07, Smart Configurator for RX V2.22.0

Outline

The products in the title have been updated as follows.

- (1) e² studio RX Smart Configurator Plug-in: From 2024-04 to 2024-07
- (2) Smart Configurator for RX: From V2.21.0 to V2.22.0

1. Products to Be Updated

- e² studio 2024-04 (RX Smart Configurator Plug-in 2024-04) and earlier
- Smart Configurator for RX V2.21.0 and earlier

2. Description

The following issues have been fixed.

- Fixed AN008 setting of Continuous Scan Mode S12AD for RX140
- Fixed default value setting for PDR register of PORT H for RX140
- Fixed shared pin checking for RX26T
- Fixed exception issue when deleting a SC project containing an exported Pin.xml

For other fixes, please refer to the release notes above.

- Smart Configurator for RX
Smart Configurator for RX V2.22.0 Release Note (the note will be uploaded on July 22)
<https://www.renesas.com/software-tool/rx-smart-configurator#documents>

3. Updating the Product

3.1 e² studio

Refer to the Tool News (3. Updating the Product) at the URL below (the news will be uploaded on July 22).

<https://www.renesas.com/software-tool/e-studio#documents>

RENESAS TOOL NEWS: R20TS1041EJ0100 (July 22, 2024, issue)

e² studio Integrated Development Environment 2024-07 Update

Note: The Smart Configurator is up

3.2 CS+

- (1) Download the latest Smart Configurator for RX from the URL below and install it (V2.22.0 will be released on July 22).

<https://www.renesas.com/rx-smart-configurator#downloads>

Smart Configurator for RX V2.22.0

- (2) On the Windows Start menu, select Programs, Renesas Electronics CS+, and then run the Update Manager (this service will be available from July 22).

Note: If you have started CS+ with the Rapid Startup function enabled, exit CS+, and then start the Update Manager.

If the Rapid Startup function is enabled and the CS+ icon is shown in the Windows notification area, the following error occurs.

M0120001

"CubeSuiteW+.exe"

Installation is suspended because "CubeSuiteW+.exe" is running.

It will be resumed next time you start the tool.

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	July 20.24	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan
www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/