[Notes]

CS+ Integrated Development Environment

Outline

When using the CS+ IDE, take note of the problem described in this note regarding the following point.

1. The properties settings to produce files of error messages from the CC-RH compiler (for the RH850 family) returning to their initial values

1. The Properties Settings to Produce Files of Error Messages from the CC-RH Compiler (for the RH850 Family) Returning to Their Initial Values

1.1 Applicable Products

RH850 Family C Compiler Package (with IDE), versions earlier than V3.02.00

To check the version number of the product you have, refer to the following URL.

http://www.renesas.com/cubesuite+_ver

1.2 Applicable MCUs

RH850 family

1.3 Details

When a project file from a version of CS+ earlier than V3.02.00 has been set with "Yes (-Xerror_file) " selected for [Output error message file] in the [Error Output] category on the [Individual Compile Options] tabbed page is opened by CS+ V3.02.00 or a later version, the selection of [Output error message file] returns to "No". The [Error message file output folder] and [Error message file name] settings also return to their initial values.

1.4 Workaround

There is currently no way to prevent this problem.

1.5 Schedule for Fixing the Problem

This problem will be fixed in the next version in April of 2016.

Revision History

Rev.	Date	Description	
		Page	**Summary**
1.00	Apr. 01, 2016	-	First edition issued

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan

Renesas Electronics Corporation

■Inquiry

http://www.renesas.com/en-hq/support/contact.html

All trademarks and registered trademarks are the property of their respective owners.