

DA1459x Devkit-Pro Daughterboard

Design Name	DA1459x_db_fcqfn52
Ref. Number	469-08-B
Version	B4
Date	10/Nov/2023
Designer	Panos Raftopoulos


History Table		
Version	Date	Comments
	30/June/2020	Release for internal review
A	15/Sept/2020	Released for manufacturing
A2		BOM modifications: - Changed J4 as populated - Antenna matching:
A3	23/Nov/2022	<ul style="list-style-type: none"> • Z1 changed to LQP03TG1N5B02 (1.5nH) • Z2 changed to 250R05L4R3BV4S (4.3pF) • Z3 changed to GRM0335C1H2R7CA01 (2.7pF)
B	05/Apr/2023	Removed all references to da1469x mainboard Replaced J3 header with a slide switch (SW1)
B2	19/Oct/2023	Added filter for FCC Tx spurious 3rd harmonic limit: <ul style="list-style-type: none"> • Changed Z4 part number to LQP03TG2N8B02D • Changed Z5,Z6 part number to GJM0335C1HR70WB01D Changed C2 to 2.2uF Changed C3,C4,C6 part number to GRM155R60J106ME05D
B3	03/Nov/2023	Changed R12, R14 to Not Populated
B4	10/Nov/2023	Changed R12, R14 to 0 ohm Changed Y2 to Not Populated

Configuration note

NOTE box

Changes in this Version.

- TP10 FIDUCIAL
- TP11 FIDUCIAL



Renesas Electronics
N.E.O. Athinon-Patron 15
26441, Patra, Greece
tel. (+30) 2610390940
fax. (+30) 2610390941

