

To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

RENESAS TECHNICAL UPDATE

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan
Renesas Technology Corp.

Product Category	MPU/MCU		Document No.	TN-SH7-A716A/E	Rev.	1.00
Title	Error correction of DACK signal of the hardware manual		Information Category	Technical Notification		
Applicable Product	SH7709S Group SH7729R Group	Lot No.	Reference Document	SH7709S hardware manual Rev5.00 (REJ09B0081-0500) SH7729R hardware manual Rev5.00 (REJ09B0091-0500)		
		All				

There are error correction of DACK signal of the hardware manuals.

(a) SH7709S hardware manual Rev5.00 (REJ09B0081-0500)

Page 329 of 760 Figure 11.1 Block Diagram of DMAC etc.

Original: $\overline{\text{DACK0}}$, $\overline{\text{DACK1}}$

Amended: DACK0, DACK1

(b) SH7729R hardware manual Rev5.00 (REJ09B0091-0500)

Page 371 of 806 Figure 12.1 Block Diagram of DMAC etc.

Original: $\overline{\text{DACK0}}$, $\overline{\text{DACK1}}$

Amended: DACK0, DACK1