

---

# **PRODUCT ADVISORY**

## **Data Sheet Specification Change for Intersil Product ISL9230\***

**Refer to:  
PA11071**

**Date: July 22, 2011**

July 22, 2011

To: Our Valued Intersil Customer

Subject: **Data Sheet Specification Change for Intersil Product ISL9230\***

This advisory is to inform you that Intersil has changed the data sheet specification for the listed ISL9230\* products. The changes align the Programmed Fast Charge Current range in the Recommended Operating Conditions section with the Electrical Specifications table and correct verbiage in the State Diagram section as to the CHG state in case of an over temp condition. The updated data sheet is available on the Intersil web site at <http://www.intersil.com/data/fn/fn7642.pdf>.

Products affected: **ISL9230IRZ ISL9230IRZ-T**

The data sheet specification change is as follows:

Recommended Operating Conditions	Current	New
Programmed Fast Charge Current	200mA to 1500mA	<b>300mA</b> to 1500mA

There will be no change in external marking of the packaged parts. There have been no changes made to the silicon or device itself.

Intersil will take all necessary actions to conform to agreed upon customer requirements and to ensure the continued high quality and reliability of products being supplied. Customers may expect to continue receiving product processed to the same established conditions and systems used for manufacturing of material supplied today.

If you have concerns with this advisory, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,



Jon Brewster  
Intersil Corporation

PA11071

CC: J. Touvell C. Chiraphanda L. Bradley