

---

# **PRODUCT ADVISORY**

## **Data Sheet Specification Correction for Intersil Product ISL98001\***

**Refer to:  
PA10097**

**Date: September 21, 2010**

September 21, 2010

To: Our Valued Intersil Customers

Subject: **Data Sheet Specification Correction for Intersil Product ISL98001\***

This advisory is to inform you that Intersil has updated the data sheet specification for the listed ISL98001\* products. The change to the  $\theta_{JA}$  value in the Thermal Information section aligns the data sheet with the product characteristics. Modifications to the data sheet specification incorporating the change are complete. The updated data sheet, FN6148 dated September 21, 2010, is available on the Intersil web site at <http://www.intersil.com/data/fn/fn6148.pdf>.

Products affected:

ISL98001CQZ-140	ISL98001CQZ-210	ISL98001CQZ-R5296
ISL98001CQZ-170	ISL98001CQZ-275	ISL98001IQZ-140

Data sheet specification changes are as follows:

Thermal Resistance - $\theta_{JA}$	Current Value	New Value	Units
128 Ld MQFP	30	55	°C/W

Intersil will take all necessary actions to conform to customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to continue receiving product processed to the same established conditions and systems used for screening of material supplied today.

If you have concerns with this change notice, Intersil must hear from you immediately. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

*Jon Brewster*

Jon Brewster  
Intersil Corporation

PA10097

CC: J. Touvell D. Nguyen K. Tucker