## Old Company Name in Catalogs and Other Documents

On April 1<sup>st</sup>, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: http://www.renesas.com

April 1<sup>st</sup>, 2010 Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (http://www.renesas.com)

Send any inquiries to http://www.renesas.com/inquiry.

## HITACHI SEMICONDUCTOR TECHNICAL UPDATE

Classification of Production	MPU				No	TN-SH7-398A/E	
THEME	SH /6 / /-INIC notice correct		Classification of Information	<ol> <li>Spec change</li> <li>Supplement of</li> <li>Documents</li> <li>Limitation of Use</li> </ol>		<ol> <li>Change of Mask</li> <li>Change of Production Line</li> </ol>	
PRODUCT NAME	L HD6417622	Lot No.			re manual	Rev.	Effective Date
		All	Reference Documents	SH7622 Hardwar		Rev.2.0	Longtime

There is correction of INTC notice in SH7622 hardware manual.

Point page : P.150, ICR0.bit-1:IRQE Description Note

Before correction :

Note: \*Once use has been enabled(by setting IRQE to 1), do not change the IRQE setting until A power-on reset is executed.

After correction :

Note: \* This bit should be written to 1 in the initialization procedure of a power-on reset, and do not change its value.