



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road  
San Jose, CA 95138

---

## PRODUCT DISCONTINUANCE NOTICE# CQ-17-02 (R1)

ISSUE DATE: July 4, 2017

LAST BUY DATE: June 2, 2018

LAST SHIP DATE: September 2, 2018

**Revision to this PDN is to amend some of the replacement part#. Last buy date and last ship date remain unchanged.**

### REASON FOR DISCONTINUANCE:

The sales activity has declined to a level that warrants the discontinuance of these products. Some of these devices may have an alternate standard device or a suggested functional replacement.

Attached is a list of affected parts with any potential drop in replacement parts or suggested functional replacement parts.

Customers should contact IDT within 90 days of receipt of this notification if they have any additional questions or concerns related to this Product Discontinuance Notice. You may contact your local IDT Sales office listed on our web site at [www.IDT.com](http://www.IDT.com) or the marketing contact listed below:

<b>NET</b>	<a href="mailto:clocks@idt.com">clocks@idt.com</a>
<b>SPO</b>	Carl May 408-284-2718 <a href="mailto:carl.may@idt.com">carl.may@idt.com</a>
<b>MMT</b>	Victor Abarca 408-284-6578 <a href="mailto:victor.abarca@idt.com">victor.abarca@idt.com</a>
<b>ACP</b>	Matt Jones 408-360-5622 <a href="mailto:matt.jones@idt.com">matt.jones@idt.com</a>
<b>FCP</b>	Leroy Sutter 408-763-2066 <a href="mailto:leroy.sutter@idt.com">leroy.sutter@idt.com</a>
<b>RIS</b>	Trevor Hiatt 408-284-4530 <a href="mailto:trevor.hiatt@idt.com">trevor.hiatt@idt.com</a>

Final orders may be submitted at any time prior to the last buy date indicated above. All orders shall be subject to acceptance per IDT standard terms and conditions.

Device to be Discontinued	Drop in Replacement	Functional Replacement	Replacement Part Availability	Product Group
709349L6PFG	None	None	N/A	SPO
709349L6PFG8	None	None	N/A	SPO
709349L7PFGI	None	None	N/A	SPO
709349L7PFGI8	None	None	N/A	SPO
70EBP1308	None	None	N/A	RIS
70P254L55BYGI	None	None	N/A	SPO
70P254L55BYGI8	None	None	N/A	SPO
70V7319S166BCGI	None	None	N/A	SPO
70V9389L7PRFG	None	None	N/A	SPO
70V9389L7PRFG8	None	None	N/A	SPO
72200L10TPG	None	None	N/A	SPO
72210L10TPG	None	None	N/A	SPO
72420L10TPG	None	None	N/A	SPO
72821L10PFG	None	None	N/A	SPO
72821L10PFG8	None	None	N/A	SPO
72T36115L4-4BBG	None	None	N/A	SPO
72V70180PFG	None	None	N/A	SPO
72V70180PFG8	None	None	N/A	SPO
72V73260BBG	None	None	N/A	SPO
72V73260BBG8	None	None	N/A	SPO
80KSW0002ALG	None	80RXS1632AALG	Available now	RIS
80KSW0002ALG8	None	80RXS1632AALG	Available now	RIS
80KSW0002ALGI	None	80RXS1632AALGI	Available now	RIS
80KSW0002ALGI8	None	80RXS1632AALG	Available now	RIS
80KSW0002AR	None	80RXS1632AALG	Available now	RIS
80KSW0002ARI	None	80RXS1632AALGI	Available now	RIS
80KSW0002HMG	None	80RXS1632AALG	Available now	RIS
80KSW0002HMG1	None	80RXS1632AALGI	Available now	RIS
80KSW0004AR	None	80RXS1632AALG	Available now	RIS
80KSW0004ARI	None	80RXS1632AALGI	Available now	RIS
80KSW0005BRI-FRE	None	None	N/A	RIS
82P2910ABB	None	None	N/A	SPO
82P2910ABB8	None	None	N/A	SPO
82V2058LBBG	None	None	N/A	SPO
89H12NT12G2ZCHL	89H12NT12G2ZCHLG	None	Available now	ACP
89H12NT12G2ZCHL8	89H12NT12G2ZCHLG8	None	Available now	ACP
89H12NT12G2ZCHLI	89H12NT12G2ZCHLGI	None	Available now	ACP
89H12NT12G2ZCHLI8	89H12NT12G2ZCHLGI8	None	Available now	ACP
89H16NT16G2ZCHL	89H16NT16G2ZCHLG	None	Available now	ACP
89H16NT16G2ZCHL8	89H16NT16G2ZCHLG8	None	Available now	ACP
89H16NT16G2ZCHLI	89H16NT16G2ZCHLGI	None	Available now	ACP
89H16NT16G2ZCHLI8	89H16NT16G2ZCHLGI8	None	Available now	ACP
89H16T16AG2ZCHL	89H16T16AG2ZCHLG	None	Available now	ACP
89H16T16AG2ZCHL8	89H16T16AG2ZCHLG8	None	Available now	ACP
89H16T16AG2ZCHLI	89H16T16AG2ZCHLGI	None	Available now	ACP
89H16T16AG2ZCHLI8	89H16T16AG2ZCHLGI8	None	Available now	ACP
89H24NT24G2ZBHL	89H24NT24G2ZBHLG	None	Available now	ACP
89H24NT24G2ZBHL8	89H24NT24G2ZBHLG8	None	Available now	ACP
89H24NT24G2ZBHLI	89H24NT24G2ZBHLGI	None	Available now	ACP
89H24NT24G2ZBHLI8	89H24NT24G2ZBHLGI8	None	Available now	ACP
89H24NT24G2ZCHL	89H24NT24G2ZCHLG	None	Available now	ACP
89H24NT24G2ZCHL8	89H24NT24G2ZCHLG8	None	Available now	ACP
89H24NT24G2ZCHLI	89H24NT24G2ZCHLGI	None	Available now	ACP
89H24NT24G2ZCHLI8	89H24NT24G2ZCHLGI8	None	Available now	ACP
89H24NT6AG2ZBHL	89H24NT6AG2ZBHLG	None	Available now	ACP
89H24NT6AG2ZBHL8	89H24NT6AG2ZBHLG8	None	Available now	ACP
89H24NT6AG2ZBHLI	89H24NT6AG2ZBHLGI	None	Available now	ACP
89H24NT6AG2ZBHLI8	89H24NT6AG2ZBHLGI8	None	Available now	ACP
89H24NT6AG2ZCHL	89H24NT6AG2ZCHLG	None	Available now	ACP
89H24NT6AG2ZCHL8	89H24NT6AG2ZCHLG8	None	Available now	ACP
89H24NT6AG2ZCHLI	89H24NT6AG2ZCHLGI	None	Available now	ACP
89H24NT6AG2ZCHLI8	89H24NT6AG2ZCHLGI8	None	Available now	ACP
89H32H8G2ZCBL	89H32H8G2ZCBLG	None	Available now	ACP
89H32H8G2ZCBL8	89H32H8G2ZCBLG8	None	Available now	ACP
89H32H8G2ZCBLI	89H32H8G2ZCBLGI	None	Available now	ACP
89H32H8G2ZCBLI8	89H32H8G2ZCBLGI8	None	Available now	ACP
89H32H8G3YCHL	89H32H8G3YCHLG	None	Available now	ACP
89H32H8G3YCHL8	89H32H8G3YCHLG8	None	Available now	ACP
89H32H8G3YCHLI	89H32H8G3YCHLGI	None	Available now	ACP
89H32H8G3YCHLI8	89H32H8G3YCHLGI8	None	Available now	ACP
89H32NT24AG2ZBHL	89H32NT24AG2ZBHLG	None	Available now	ACP
89H32NT24AG2ZBHL8	89H32NT24AG2ZBHLG8	None	Available now	ACP
89H32NT24AG2ZBHLI	89H32NT24AG2ZBHLGI	None	Available now	ACP
89H32NT24AG2ZBHLI8	None	None	N/A	ACP
89H32NT24AG2ZCHL	89H32NT24AG2ZCHLG	None	Available now	ACP
89H32NT24AG2ZCHL8	89H32NT24AG2ZCHLG8	None	Available now	ACP
89H32NT24AG2ZCHLI	89H32NT24AG2ZCHLGI	None	Available now	ACP
89H32NT24AG2ZCHLI8	None	None	N/A	ACP
89H32NT24BG2ZBHL	89H32NT24BG2ZBHLG	None	Available now	ACP
89H32NT24BG2ZBHL8	89H32NT24BG2ZBHLG8	None	Available now	ACP
89H32NT24BG2ZBHLI	89H32NT24BG2ZBHLGI	None	Available now	ACP
89H32NT24BG2ZBHLI8	None	None	N/A	ACP
89H32NT24BG2ZCHL	89H32NT24BG2ZCHLG	None	Available now	ACP
89H32NT24BG2ZCHL8	89H32NT24BG2ZCHLG8	None	Available now	ACP
89H32NT24BG2ZCHLI	89H32NT24BG2ZCHLGI	None	Available now	ACP
89H32NT24BG2ZCHLI8	None	None	N/A	ACP
89H32NT8AG2ZBHL	89H32NT8AG2ZBHLG	None	Available now	ACP
89H32NT8AG2ZBHL8	89H32NT8AG2ZBHLG8	None	Available now	ACP
89H32NT8AG2ZBHLI	89H32NT8AG2ZBHLGI	None	Available now	ACP

Device to be Discontinued	Drop in Replacement	Functional Replacement	Replacement Part Availability	Product Group
89H32NT8AG2ZBHLI8	89H32NT8AG2ZBHLG18	None	Available now	ACP
89H32NT8AG2ZCHL	89H32NT8AG2ZCHLG	None	Available now	ACP
89H32NT8AG2ZCHL8	89H32NT8AG2ZCHLG8	None	Available now	ACP
89H32NT8AG2ZCHLI	89H32NT8AG2ZCHLGI	None	Available now	ACP
89H32NT8AG2ZCHLI8	89H32NT8AG2ZCHLGI8	None	Available now	ACP
89H32NT8BG2ZBHL	89H32NT8BG2ZBHLG	None	Available now	ACP
89H32NT8BG2ZBHL8	89H32NT8BG2ZBHLG8	None	Available now	ACP
89H32NT8BG2ZBHLI	89H32NT8BG2ZBHLGI	None	Available now	ACP
89H32NT8BG2ZBHLI8	89H32NT8BG2ZBHLGI8	None	Available now	ACP
89H32NT8BG2ZCHL	89H32NT8BG2ZCHLG	None	Available now	ACP
89H32NT8BG2ZCHL8	89H32NT8BG2ZCHLG8	None	Available now	ACP
89H32NT8BG2ZCHLI	89H32NT8BG2ZCHLGI	None	Available now	ACP
89H32NT8BG2ZCHLI8	89H32NT8BG2ZCHLGI8	None	Available now	ACP
89H32T8G2ZCBL	89H32T8G2ZCBLG	None	Available now	ACP
89H32T8G2ZCBL8	89H32T8G2ZCBLG8	None	Available now	ACP
89H32T8G2ZCBLI	89H32T8G2ZCBLGI	None	Available now	ACP
89H32T8G2ZCBLI8	89H32T8G2ZCBLGI8	None	Available now	ACP
89H34H16G2ZCBL	89H34H16G2ZCBLG	None	Available now	ACP
89H34H16G2ZCBLI	89H34H16G2ZCBLGI	None	Available now	ACP
89H48H12AG2ZCBL	89H48H12AG2ZCBLG	None	Available now	ACP
89H48H12AG2ZCBLI	89H48H12AG2ZCBLGI	None	Available now	ACP
89H48H12BG2ZCBL	89H48H12BG2ZCBLG	None	Available now	ACP
89H48H12BG2ZCBLI	89H48H12BG2ZCBLGI	None	Available now	ACP
89H48H12G2ZCBL	89H48H12G2ZCBLG	None	Available now	ACP
89H48H12G2ZCBL8	89H48H12G2ZCBLG8	None	Available now	ACP
89H48H12G2ZCBLI	89H48H12G2ZCBLGI	None	Available now	ACP
89H48H12G2ZCBLI8	89H48H12G2ZCBLGI8	None	Available now	ACP
89H48H12G2ZDBL	89H48H12G2ZDBLG	None	Available now	ACP
89H48H12G2ZDBL8	89H48H12G2ZDBLG8	None	Available now	ACP
89H48H12G2ZDBLI	89H48H12G2ZDBLGI	None	Available now	ACP
89H48H12G2ZDBLI8	89H48H12G2ZDBLGI8	None	Available now	ACP
89H48H12G3YCHL	89H48H12G3YCHLG	None	Available now	ACP
89H48H12G3YCHL8	89H48H12G3YCHLG8	None	Available now	ACP
89H48H12G3YCHLI	89H48H12G3YCHLGI	None	Available now	ACP
89H48H12G3YCHLI8	89H48H12G3YCHLGI8	None	Available now	ACP
89H48T12G2ZCBL	89H48T12G2ZCBLG	None	Available now	ACP
89H48T12G2ZCBL8	89H48T12G2ZCBLG8	None	Available now	ACP
89H48T12G2ZCBLI	89H48T12G2ZCBLGI	None	Available now	ACP
89H48T12G2ZCBLI8	89H48T12G2ZCBLGI8	None	Available now	ACP
89H48T12G2ZDBL	89H48T12G2ZDBLG	None	Available now	ACP
89H48T12G2ZDBL8	89H48T12G2ZDBLG8	None	Available now	ACP
89H48T12G2ZDBLI	89H48T12G2ZDBLGI	None	Available now	ACP
89H48T12G2ZDBLI8	89H48T12G2ZDBLGI8	None	Available now	ACP
89H64H16AG2ZCBL	89H64H16AG2ZCBLG	None	Available now	ACP
89H64H16AG2ZCBLI	89H64H16AG2ZCBLGI	None	Available now	ACP
89H64H16G2ZCBL	89H64H16G2ZCBLG	None	Available now	ACP
89H64H16G2ZCBLI	89H64H16G2ZCBLGI	None	Available now	ACP
89H64H16G3YBBLG	89H64H16G3YCBLG	None	Available now	ACP
89H64H16G3YCBL	89H64H16G3YCBLG	None	Available now	ACP
89H64H16G3YCBLI	89H64H16G3YCBLGI	None	Available now	ACP
89HAL808G2ZBHL	None	None	N/A	ACP
89HAL808G2ZBHL8	None	None	N/A	ACP
89HAL808G2ZBHLG	None	None	N/A	ACP
89HAL808G2ZBHLG8	None	None	N/A	ACP
89HAL808G2ZBHLGI	None	None	N/A	ACP
89HAL808G2ZBHLGI8	None	None	N/A	ACP
89HAL808G2ZBHLI	None	None	N/A	ACP
89HAL808G2ZBHLI8	None	None	N/A	ACP
89HAL808G2ZCHL	None	None	N/A	ACP
89HAL808G2ZCHL8	None	None	N/A	ACP
89HAL808G2ZCHLG	None	None	N/A	ACP
89HAL808G2ZCHLG8	None	None	N/A	ACP
89HAL808G2ZCHLI	None	None	N/A	ACP
89HAL808G2ZCHLI8	None	None	N/A	ACP
89HI0524G2P5ZCALG	None	None	N/A	ACP
89HI0524G2P5ZCALG8	None	None	N/A	ACP
89HMPEB383ZBNQ	None	89HPEB383ZBEMG	Available now	ACP
89HMPEB383ZBNQ8	None	89HPEB383ZBEMG8	Available now	ACP
89HMPEB383ZBNQG	None	89HPEB383ZBEMG	Available now	ACP
89HMPEB383ZBNQG8	None	89HPEB383ZBEMG8	Available now	ACP
89HMPEB383ZBNQGI	None	89HPEB383ZBEMGI	Available now	ACP
89HMPEB383ZBNQGI8	None	89HPEB383ZBEMGI8	Available now	ACP
89HMPEB383ZBNQI	None	89HPEB383ZBEMGI	Available now	ACP
89HMPEB383ZBNQI8	None	89HPEB383ZBEMGI8	Available now	ACP
89HP0504PZBAB	89HP0504PZBAG	None	Available now	ACP
89HP0504PZBAB8	89HP0504PZBAG8	None	Available now	ACP
89HP0504PZBABI	89HP0504PZBAGI8	None	Available now	ACP
89HP0504PZBABI8	89HP0504PZBAGI8	None	Available now	ACP
89HP0508PZBAB	89HP0508PZBAG	None	Available now	ACP
89HP0508PZBAB8	89HP0508PZBAG8	None	Available now	ACP
89HP0508PZBABI	89HP0508PZBAGI	None	Available now	ACP
89HP0508PZBABI8	89HP0508PZBAGI8	None	Available now	ACP
89HP0604RZBAB	89HP0604RZBAG	None	Available now	ACP
89HP0604RZBAB8	89HP0604RZBAG8	None	Available now	ACP
89HP0604RZBABI	89HP0604RZBAGI8	None	Available now	ACP
89HP0604RZBABI8	89HP0604RZBAGI8	None	Available now	ACP
89HP0604SZBAB	89HP0604SZBAG	None	Available now	ACP
89HP0604SZBAB8	89HP0604SZBAG8	None	Available now	ACP
89HP0604SZBABI	89HP0604SZBAGI	None	Available now	ACP
89HP0604SZBABI8	89HP0604SZBAGI8	None	Available now	ACP
89HP0604XZBAB	89HP0604XZBAG	None	Available now	ACP







Device to be Discontinued	Drop in Replacement	Functional Replacement	Replacement Part Availability	Product Group
TSI340-66CQY	None	None	N/A	ACP
TSI350-66CQ	TSI350-66CQY	None	Available now	ACP
TSI382-66CQY	None	TSI382-66ILV	Available now	ACP
TSI382-66IL	TSI382-66ILV	None	Available now	ACP
TSI382A-66CQY	None	Tsi382-66ILV	Available now	ACP
TSI568A-10GCL	None	80RXS1632AALG	Available now	RIS
TSI568A-10GCLY	None	80RXS1632AALG	Available now	RIS
TSI568A-10GIL	None	80RXS1632AALGI	Available now	RIS
TSI568A-10GILY	None	80RXS1632AALGI	Available now	RIS
TSI572-10GCLV	None	80RXS1632AALG	Available now	RIS
TSI572-10GILV	None	80RXS1632AALGI	Available now	RIS
TSI574-10GCL	None	80RXS1632AALG	Available now	RIS
TSI574-10GCLV	None	80RXS1632AALG	Available now	RIS
TSI574-10GIL	None	80RXS1632AALGI	Available now	RIS
TSI574-10GILV	None	80RXS1632AALGI	Available now	RIS
TSI577-10GCLV	None	80RXS1632AALG	Available now	RIS
TSI577-10GILV	None	80RXS1632AALGI	Available now	RIS
TSI578-10GCL	None	80RXS1632AALG	Available now	RIS
TSI578-10GCLH	None	80RXS1632AALG	Available now	RIS
TSI578-10GCLV	None	80RXS1632AALG	Available now	RIS
TSI578-10GCLY	None	80RXS1632AALG	Available now	RIS
TSI578-10GIL	None	80RXS1632AALGI	Available now	RIS
TSI578-10GILH	None	80RXS1632AALGI	Available now	RIS
TSI578-10GILV	None	80RXS1632AALGI	Available now	RIS
TSI578-10GILY	None	80RXS1632AALGI	Available now	RIS
TSI578A-10GIL	None	80RXS1632AALGI	Available now	RIS
TSI578A-10GILH	None	80RXS1632AALGI	Available now	RIS
TSI578A-10GILV	None	80RXS1632AALGI	Available now	RIS
TSI578A-10GILY	None	80RXS1632AALGI	Available now	RIS
TSI578A-10GILY/AL	None	80RXS1632AALGI	Available now	RIS
TSI578A-ILH	None	80RXS1632AALGI	Available now	RIS
TSI578A-ILVY	None	80RXS1632AALGI	Available now	RIS
TSI578-CLH	None	80RXS1632AALG	Available now	RIS
TSI578-CLVY	None	80RXS1632AALG	Available now	RIS
TSI578-ILH	None	80RXS1632AALGI	Available now	RIS
TSI578-ILVY	None	80RXS1632AALGI	Available now	RIS
TSI711-8GCLY	None	TSI721A1-16GCLV	Available now	RIS
TSI711-8GIL	None	TSI721A1-16GCLV	Available now	RIS
TSI711-8GILY	None	TSI721A1-16GILV	Available now	RIS
XLHA35048.000JX4I	None	None	N/A	FCP
XLHA35048.000JX4I8	None	None	N/A	FCP
XLHA35050.000JX4I	None	None	N/A	FCP
XLHA35050.000JX4I8	None	None	N/A	FCP
XLHA35156.250J54I	None	None	N/A	FCP
XLHA35156.250J54I8	None	None	N/A	FCP
XLHA35156.250JU4I	None	None	N/A	FCP
XLHA35156.250JU4I8	None	None	N/A	FCP
XLHB35156.250JU4I	None	None	N/A	FCP
XLHB35156.250JU4I8	None	None	N/A	FCP
XLPA35161.13AJX6I	None	None	N/A	FCP
XLPA35161.13AJX6I8	None	None	N/A	FCP