

Product Lifecycle Notice

Subject: Product Discontinuance / Obsolescence Notification Products

Publication Date: 4/12/2016

Revision Description:

Initial release

You are hereby provided notice that the Intersil products included on the attached parts list are being discontinued. As a valued customer, and one that has previously purchased one or more of such parts, Intersil Corporation is pleased to offer you a final life-of-type procurement for these parts. Recognizing that you will need some time to analyze your requirements, Intersil will accept orders for these products through the LTB (Life of Type Buy) / WITHDRAWN date provided in the attached list. All shipments under such orders shall be scheduled no later than the SHIP / OBSOLETE date provided. Intersil will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please review the lists and make adjustments as necessary in your database.

The information contained herein is intended for the recipients use only. Please limit the distribution of this material to those individuals within your immediate organization having a need to act upon the information.

If you are considering a redesign, and require assistance, please contact your local Sales or Rep office, or the Intersil Corporate Line, 1-888-468-3774, for our Central Applications Department.

Regards,



Jeffrey Touvell

Intersil Corporation

Exact Intersil Part # No other variation is being impacted.	Notice PLC16037 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
29104BJA	4/12/2016	10/12/2016	4/12/2017	8403602JA or 8403603JA
EL4583CSZ-T7S2687	4/12/2016	10/12/2016	4/12/2017	EL4583CSZ-T7
EL5104ISZ	4/12/2016	10/12/2016	4/12/2017	EL5104IWZ-T7
EL5104ISZ-T13	4/12/2016	10/12/2016	4/12/2017	EL5104IWZ-T7
EL5104ISZ-T7	4/12/2016	10/12/2016	4/12/2017	EL5104IWZ-T7
HA1-5330-5	4/12/2016	10/12/2016	4/12/2017	None
HI3-0507-5Z	4/12/2016	10/12/2016	4/12/2017	HI3-0547-5Z
HI3-0516-5Z	4/12/2016	10/12/2016	4/12/2017	DG406DJZ/DG407DJZ
HI3-0546-5Z	4/12/2016	10/12/2016	4/12/2017	HI9P0546-9Z/HI4P0546-5Z
HI3-5051-5Z	4/12/2016	10/12/2016	4/12/2017	HI9P0501-9Z
HI4P0509-5Z	4/12/2016	10/12/2016	4/12/2017	DG409DYZ
HI4P0509-5Z96	4/12/2016	10/12/2016	4/12/2017	DG409DYZ
HI4P0547-5Z	4/12/2016	10/12/2016	4/12/2017	HI3-0547-5Z
HI9P0509-5Z96	4/12/2016	10/12/2016	4/12/2017	DG409DYZ
HSP50016JC-52	4/12/2016	10/12/2016	4/12/2017	None
HSP50016JM-5296R3571	4/12/2016	10/12/2016	4/12/2017	None
HSP50110JC-52	4/12/2016	10/12/2016	4/12/2017	None
HSP50110JC-52Z	4/12/2016	10/12/2016	4/12/2017	None
HSP50110JI-52	4/12/2016	10/12/2016	4/12/2017	None
HSP50110JI-52Z	4/12/2016	10/12/2016	4/12/2017	None
ISL22313TFU10Z	4/12/2016	10/12/2016	4/12/2017	ISL22313UFU10Z
ISL22313TFU10Z-TK	4/12/2016	10/12/2016	4/12/2017	ISL22313UFU10Z-TK
ISL78600ANZR5573	4/12/2016	10/12/2016	4/12/2017	ISL78600ANZ
ISL78600ANZ-TR5573	4/12/2016	10/12/2016	4/12/2017	ISL78600ANZ-T
ISL95901IRZ	4/12/2016	10/12/2016	4/12/2017	None
ISL95901IRZ-T	4/12/2016	10/12/2016	4/12/2017	None
TW8804-LC3-GRSHV	4/12/2016	5/12/2016	5/12/2016	TW8804-LC3-GRSH
TW8806EP-PB2-GRSHI	4/12/2016	4/12/2016	4/12/2016	TW8806EP-PB2-GRS
TW8806EP-PB2-GRSV	4/12/2016	10/12/2016	4/12/2017	TW8806EP-PB2-GRS
X28HC256JI-90R5697	4/12/2016	10/12/2016	4/12/2017	None
X9C102SIZT2	4/12/2016	10/12/2016	4/12/2017	X9C102SIZT1