

## Product Change Notice (PCN)

**Subject:** Design Change for the Listed ISL95853\* and ISL95854\* Intersil Products

**Publication Date:** 5/13/2016

**Effective Date:** 8/13/2016

**Revision Description:**

Initial Release

**Description of Change:**

This notice is to advise our customers of a minor design revision for the products listed below.

Products impacted by the change are:

ISL95853HRZ	ISL95853IRZ	ISL95854HRZ-TK	ISL95854IRZ-T
ISL95853HRZ-T	ISL95853IRZ-T	ISL95854HRZ-TS2568	
ISL95853HRZ-TK	ISL95854HRZ	ISL95854HRZ-TS2722	
ISL95853HRZ-TS2568	ISL95854HRZ-T	ISL95854IRZ	

**Reason for Change:**

Product design implemented to fix a decay to 0V issue where the DAC can underflow to 1FF hex if a setVIDfast or slow command is sent right as the DAC is decaying from 01 hex to 00 hex.

**Impact on fit, form, function, quality & reliability:**

The change will have no other impact on the form, fit, function, quality, reliability and environmental compliance of the devices. The new version is pin-to-pin compatible, and external configuration and components are exactly same and a drop-in replacement for the previous version.

**Product Identification:**

There will be no change in the external marking of the packaged parts or to the product data sheet electrical specification. Product affected by this change is identifiable via Intersil's internal traceability system.

**Qualification status:** Complete, functional validation performed

**Sample availability:** 5/13/2016

**Device material declaration:** Available upon request

*Questions or requests pertaining to this change notice, including additional data or samples, must be sent to Intersil within 30 days of the publication date.*

For additional information regarding this notice, please contact your regional change coordinator (below)			
Americas: <a href="mailto:PCN-US@INTERSIL.COM">PCN-US@INTERSIL.COM</a>	Europe: <a href="mailto:PCN-EU@INTERSIL.COM">PCN-EU@INTERSIL.COM</a>	Japan: <a href="mailto:PCN-JP@INTERSIL.COM">PCN-JP@INTERSIL.COM</a>	Asia Pac: <a href="mailto:PCN-APAC@INTERSIL.COM">PCN-APAC@INTERSIL.COM</a>