

RI600V4 Timer template file

As of October, 2017

Timer template file	Supported MCU
rx610.tpl	RX600 series RX610 group
rx62t.tpl	RX600 series RX62T group
rx62n.tpl	RX600 series RX62G group RX600 series RX62N group RX600 series RX621 group
rx630.tpl	RX700 series RX71M group *1 RX600 series RX65N group *1 RX600 series RX651 group *1 RX600 series RX64M group *1 RX600 series RX630 group RX600 series RX63N group RX600 series RX631 group RX600 series RX634 group RX600 series RX63T group RX200 series RX21A group RX200 series RX230 group RX200 series RX231 group RX200 series RX23T group RX200 series RX24T group RX200 series RX24U group
rx210.tpl	RX200 series RX210 group RX200 series RX220 group RX100 series RX110 group *1 RX100 series RX111 group *1 RX100 series RX113 group *1 RX100 series RX130 group *1

*1 In the system configuration file, "CMT 2" and "CMT 3" should not be specified for clock.timer.